

OIL ANALYSIS REPORT

Sample Rating Trend



Area TBN TBN-QC10 Component **Oil** Fluid {not provided} (--- GAL)

DIAGNOSIS


			205																													
	1			1	1	L			1		1	1	L	L	U			1	1	1	L	1	1	1	I.	L	I.	Ι.		U		
111		2	1.			÷	1.	١.	١.	١.				4	÷	1	١.	١.							4	4		4	÷	1	1.	1



SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Date		Client Info		24 Aug 2023	23 Aug 2023	23 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	\$	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



OIL ANALYSIS REPORT



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 25 Aug 2023 501 Madison Ave Lab Number : Q0004I8W Diagnosed : 25 Aug 2023 Cary, NC Unique Number : 16010847 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 F: (919)379-4050

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: WCLS CARY NC ? - WEACARQA