


OIL ANALYSIS REPORT

Sample Rating Trend





AutoTAN-2-QC
Component
Oil

TAN Auto

Fluid {not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		25 Aug 2023	24 Aug 2023	24 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS







Laboratory Sample No. Lab Number

Unique Number : 16010985

-0.8

: Q0004I9P

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 28 Aug 2023 Diagnosed : 28 Aug 2023

Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: (919)379-4102 F: (919)379-4050