


## **OIL ANALYSIS REPORT**

Sample Rating Trend



TBN Machine Id TBN-QC10

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


044451 5 1415054						
SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		25 Aug 2023	25 Aug 2023	24 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2


SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



## **OIL ANALYSIS REPORT**

## **GRAPHS**







Certificate L2367

Laboratory Sample No. Lab Number Test Package : TEST

Unique Number : 16010988

: Q0004I9S

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 28 Aug 2023

Diagnosed : 28 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave

Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050