


# **OIL ANALYSIS REPORT**

Sample Rating Trend







## TBN Machine Id TBN-QC10

Component Oil Fluid

{not provided} (--- GAL)


DIAGNOSIS	D	A	GN	10	SI	IS
-----------	---	---	----	----	----	----

SAMPLE INFORM	MOITAN	method	limit/base	current	history1	history2
Sample Date		Client Info		27 Sep 2023	26 Sep 2023	26 Sep 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image




### **OIL ANALYSIS REPORT**

### **GRAPHS**



#### Non-ferrous Metals





Certificate L2367

Report Id: WEACARQA [WUSCAR] Q0004J28 (Generated: 10/04/2023 21:18:69) Rev: 1

Sample No. Lab Number

Laboratory Unique Number : 16017322 Test Package : TEST

: Q0004J28

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 28 Sep 2023 Diagnosed

: 28 Sep 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)