


OIL ANALYSIS REPORT

Bottom

Sample Rating Trend



TAN Auto Machine Id AutoTAN-1-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		25 Oct 2023	24 Oct 2023	24 Oct 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image

no image


no image

no image




OIL ANALYSIS REPORT


GRAPHS







Viscosity @ 40°C





Laboratory Sample No. Lab Number Test Package : TEST

Unique Number : 16036781

: Q0004KD9

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 26 Oct 2023

Diagnosed : 26 Oct 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050 Contact/Location: WCLS CARY NC? - WEACARQA