


# **OIL ANALYSIS REPORT**

#### Sample Rating Trend





### 1012 Aug2022 Sec002 Sec002 Aug2022 Aug

| SAMPLE INFORM | <b>IATION</b> | method      | limit/base | current     | history1    | history2    |
|---------------|---------------|-------------|------------|-------------|-------------|-------------|
| Sample Date   |               | Client Info |            | 27 Oct 2023 | 24 Oct 2023 | 24 Oct 2023 |
| Machine Age   | HR            | Client Info |            | 0           | 0           | 0           |
| Oil Age       | HR            | Client Info |            | 0           | 0           | 0           |
| Oil Changed   |               | Client Info |            | N/A         | N/A         | N/A         |
| Sample Status |               |             |            |             |             |             |
| SAMPLE IMAGES | \$            | method      | limit/base | current     | history1    | history2    |
| Color         |               |             |            | no image    | no image    | no image    |
| Bottom        |               |             |            | no image    | no image    | no image    |


# Area FT-IR FTIR-1-QC

Component **Oil** Fluid {not provided} (--- GAL)

## DIAGNOSIS



## **OIL ANALYSIS REPORT**



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 27 Oct 2023 501 Madison Ave Lab Number : Q0004KG5 Diagnosed : 27 Oct 2023 Cary, NC Unique Number : 16037388 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 ÷.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050