


OIL ANALYSIS REPORT

Sample Rating Trend



ICP ARCOS-2-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


| SAMPLE INFORM | MATION | method | limit/base | current | history1 | history2 |
|---------------|--------|-------------|------------|-------------|-------------|-------------|
| Sample Date | | Client Info | | 27 Oct 2023 | 27 Oct 2023 | 27 Oct 2023 |
| Machine Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | | | |

| | SAMPLE IMAGES | method | limit/base | current | history1 | history2 | |
|---|---------------|--------|------------|----------|----------|----------|--|
| , | Color | | | no image | no image | no image | |
| | Bottom | | | no image | no image | no image | |



OIL ANALYSIS REPORT

GRAPHS





Certificate L2367

Laboratory Sample No. Lab Number

: Q0004KGJ Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 27 Oct 2023 : 27 Oct 2023

Diagnosed Unique Number : 16037406 Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave

Contact: WCLS CARY NC

Cary, NC

US 27513