


## **OIL ANALYSIS REPORT**

Sample Rating Trend



ICP ARCOS-2-S-21/50

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


		12023 002023	002023 002023	002023 002023 002023	002023	
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		31 Oct 2023	31 Oct 2023	31 Oct 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	;	method	limit/base	current	history1	history2

SAMPLE IMAGES	method	limit/base	current	history1	history2	
Color			no image	no image	no image	
Bottom			no image	no image	no image	



## **OIL ANALYSIS REPORT**

## **GRAPHS**





Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 16038001 Test Package : TEST

: Q0004KNW

15

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 31 Oct 2023 Received

Diagnosed : 31 Oct 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)