

OIL ANALYSIS REPORT







TAN Auto AutoTAN-2-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


		12023 002023	002023 002023	002023 002023 10	1042023	
SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		03 Nov 2023	03 Nov 2023	02 Nov 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2


SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image




OIL ANALYSIS REPORT

GRAPHS









Laboratory Sample No. Lab Number Unique Number : 16039724 Test Package : TEST

: Q0004L00

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 06 Nov 2023 Received

: 06 Nov 2023 Diagnosed Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: (919)379-4102 F: (919)379-4050