

## **OIL ANALYSIS REPORT**


## TAN Man TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS







SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		01 Feb 2024	01 Feb 2024	01 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2

water	WC Method		NEG	NEG	NEG
SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No.

Test Package : TEST

Lab Number : Q0005B53 **Unique Number** : 16089145

Received Tested

: 01 Feb 2024 : 01 Feb 2024

Diagnosed : 01 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Report Id: WEACARQA [WUSCAR] Q0005B53 (Generated: 02/08/2024 20:20:30) Rev: 1

Page 2 of 2

T: (919)379-4102