

PROBLEM SUMMARY

Sample Rating Trend

WEAR

WEAR

Machine Id


KAESER SK 15 5194034 (S/N 1070)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL	
Copper	ppm	ASTM D5185m	>50	58	<u></u> 61	15	

Customer Id: SERPRI Sample No.: KCP33323 Lab Number: 05633658 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

09 Oct 2018 Diag: Angela Borella

WEAR



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



12 Mar 2018 Diag: Angela Borella

150



No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



KAESER SK 15 5194034 (S/N 1070)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

The copper level is abnormal. All other component wear rates are normal.

Contamination

There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		Mar2018		Oct2018 Aug20	122	
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP33323	KC76548	KCP09319
Sample Date				23 Aug 2022	09 Oct 2018	12 Mar 2018
Machine Age	hrs			30179	6646	2652
Oil Age	hrs			3862	3993	2652
Oil Changed				Not Changd	Not Changd	Changed
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	0	<1	<1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	0	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	<1	0	0
Aluminum	ppm	ASTM D5185m	>10	<1	<1	<1
Lead	ppm	ASTM D5185m	>10	0	0	1
Copper	ppm	ASTM D5185m	>50	<u></u> 58	<u>▲</u> 61	15
Tin	ppm	ASTM D5185m	>10	<1	0	0
Antimony	ppm	ASTM D5185m			0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m		0	0	1
Barium	ppm	ASTM D5185m	90	2	0	10
Molybdenum	ppm	ASTM D5185m		0	<1	0
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m	90	5	16	41
Calcium	ppm	ASTM D5185m	2	0	0	0
Phosphorus	ppm	ASTM D5185m		4	<1	40
Zinc	ppm	ASTM D5185m		39	64	37
Sulfur	ppm	ASTM D5185m		15235	14250	17954
CONTAMINANTS	3	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	0	<1	<1
Sodium	ppm	ASTM D5185m		0	8	15
Potassium	ppm	ASTM D5185m	>20	2	2	1
Water	%	ASTM D6304	>0.05	0.005	0.016	0.018
ppm Water	ppm	ASTM D6304	>500	54.8	160	180
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4µm		ASTM D7647		708	81654	18298
Particles >6µm		ASTM D7647	>1300	183	▲ 13932	△ 6369
Particles >14μm		ASTM D7647	>80	20	<u> </u>	<u> </u>
Particles >21μm		ASTM D7647	>20	6	▲ 335	13
Particles >38μm		ASTM D7647	>4	1	<u> </u>	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>/17/13	17/15/11	△ 21/18	△ 20/14
FLUID DEGRADA	ATION	method	limit/base	current	history 1	history 2

mg KOH/g ASTM D8045 0.4

Acid Number (AN)


0.37

0.368


0.411



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERTIES		method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	46	44.5	44.68	43.85
SAMPLE IMAGES		method	limit/base	current	history 1	history 2
Color						
Bottom						







Laboratory Sample No. Lab Number Unique Number : 10118179

: KCP33323 : 05633658

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Diagnosed

: 06 Sep 2022 Diagnostician : Doug Bogart

: 02 Sep 2022

Test Package : IND 2 (Additional Tests: KF, PrtCount)

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

To discuss this sample report, contact Customer Service at 1-800-237-1369.

SERVICE CENTER METALS 5850 QUALITY WAY PRINCE GEORGE, VA

USA 23875

Contact:

T: F:

Report Id: SERPRI [WUSCAR] 05633658 (Generated: 09/06/2022 18:42:07)

Contact/Location: ? ? - SERPRI