

PROBLEM SUMMARY

Sample Rating Trend



KAESER AIRCENTER SM 15 5685877 (S/N 1647)


Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status			ABNORMAL	ATTENTION	NORMAL			
Particles >6µm	ASTM D7647	>1300	12437	889	890			
Particles >14μm	ASTM D7647	>80	<u> </u>	<u>▲</u> 112	72			
Particles >21μm	ASTM D7647	>20	<u> </u>	△ 34	16			
Particles >38μm	ASTM D7647	>4	14	5	0			
Oil Cleanliness	ISO 4406 (c)	>/17/13	23/21/17	▲ 17/14	17/13			

Customer Id: SOFBED Sample No.: KCP48122 Lab Number: 05637131 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

04 Jan 2022 Diag: Angela Borella

ISO



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



25 Jan 2021 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



23 Dec 2019 Diag: Jonathan Hester

150



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

KAESER AIRCENTER SM 15 5685877 (S/N 1647)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

▲ Contamination

There is a high amount of particulates present in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		Dec201	9 Jan2021	Jan 2022 Au	g2022	
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP48122	KC95584	KCP27809
Sample Date				31 Aug 2022	04 Jan 2022	25 Jan 2021
Machine Age	hrs			11294	9584	8119
Oil Age	hrs			3805	1073	0
Oil Changed				Not Changd	Not Changd	Changed
Sample Status				ABNORMAL	ATTENTION	NORMAL
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	0	<1	0
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	<1	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	0	<1	0
Aluminum	ppm	ASTM D5185m	>10	<1	<1	0
Lead	ppm	ASTM D5185m	>10	0	<1	0
Copper	ppm	ASTM D5185m	>50	7	4	2
Tin	ppm	ASTM D5185m	>10	0	0	0
Antimony	ppm	ASTM D5185m			<1	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m		0	22	0
Barium	ppm	ASTM D5185m	90	19	27	84
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	<1	0
Magnesium	ppm	ASTM D5185m	90	55	76	84
Calcium	ppm	ASTM D5185m	2	0	1	<1
Phosphorus	ppm	ASTM D5185m		<1	5	10
Zinc	ppm	ASTM D5185m		5	4	0
Sulfur	ppm	ASTM D5185m		17594	16911	18237
CONTAMINANTS	3	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	<1	<1	0
Sodium	ppm	ASTM D5185m		14	13	0
Potassium	ppm	ASTM D5185m	>20	0	2	0
Water	%	ASTM D6304	>0.05	0.022	0.005	0.015
ppm Water	ppm	ASTM D6304	>500	228.8	57.6	158.0
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4μm		ASTM D7647		41569	5562	3178
Particles >6µm		ASTM D7647	>1300	<u> </u>	889	890
Particles >14μm		ASTM D7647	>80	<u> </u>	<u>▲</u> 112	72
Particles >21µm		ASTM D7647	>20	<u>^</u> 261	<u>▲</u> 34	16
Particles >38µm		ASTM D7647	>4	<u> </u>	5	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>/17/13	23/21/17	△ 17/14	17/13
FLUID DEGRADA	ATION	method	limit/base	current	history 1	history 2


0.35



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERTIES		method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	46	45.2	45.0	43.8
SAMPLE IMAGES	3	method	limit/base	current	history 1	history 2
Color						
Bottom						







Laboratory Sample No. Lab Number Unique Number : 10126661

: KCP48122 : 05637131

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 09 Sep 2022 Diagnostician : Doug Bogart

: 08 Sep 2022

Test Package : IND 2 (Additional Tests: KF, PrtCount)

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) SOFT ROBOTICS INC

32 CROSBY DR BEDFORD, MA USA 01730

Contact: Service Manager

T:

F: