

PROBLEM SUMMARY

Sample Rating Trend

ISO


1422044 (S/N 0189333)

Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TE	EST RESULTS			
Sample Status			ABNORMAL	
Particles >6µm	ASTM D7647	>1300	10528	
Particles >14μm	ASTM D7647	>80	197	
Particles >21µm	ASTM D7647	>20	^ 67	
Particles >38µm	ASTM D7647	>4	<u>^</u> 8	
Oil Cleanliness	ISO 4406 (c)	>/17/13	<u>4</u> 24/21/15	

Customer Id: TAPSCOCA Sample No.: KCP33285 Lab Number: 05639078 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED	ACTIONS			
Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT



1422044 (S/N 0189333)

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.


Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Sep2022		
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP33285		
Sample Date				11 Sep 2022		
Machine Age	hrs			9424		
Oil Age	hrs			4000		
Oil Changed				Changed		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	5		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>3	0		
Titanium	ppm	ASTM D5185m	>3	0		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m		<1		
Lead	ppm	ASTM D5185m	>10	0		
Copper	ppm	ASTM D5185m		3		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m	>10	0		
Cadmium		ASTM D5185m		0		
	ppm	ASTIVI DS 103III		Ü		
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m	0	0		
Barium	ppm	ASTM D5185m	90	2		
Molybdenum	ppm	ASTM D5185m	0	0		
Manganese	ppm	ASTM D5185m		1		
Magnesium	ppm	ASTM D5185m	100	38		
Calcium	ppm	ASTM D5185m	0	<1		
Phosphorus	ppm	ASTM D5185m	0	3		
Zinc	ppm	ASTM D5185m	0	50		
Sulfur	ppm	ASTM D5185m	23500	18685		
CONTAMINANTS	1	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	1		
Sodium	ppm	ASTM D5185m		19		
Potassium	ppm	ASTM D5185m	>20	<1		
Water	%	ASTM D6304	>0.05	0.030		
ppm Water	ppm	ASTM D6304	>500	306.6		
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4μm		ASTM D7647		144143		
Particles >6µm		ASTM D7647	>1300	10528		
Particles >14µm		ASTM D7647	>80	197		
Particles >21µm		ASTM D7647	>20	^ 67		
Particles >38µm		ASTM D7647	>4	<u>^</u> 8		
Particles >71µm		ASTM D7647	>3	1		
Oil Cleanliness		ISO 4406 (c)	>/17/13	<u> 24/21/15</u>		
FLUID DEGRADA	TION	method	limit/base	current	history 1	history 2
Acid Number (AN)	mg KOH/g	ASTM D8045	1.0	0.35		



OIL ANALYSIS REPORT





Ferrous Alloys	Particle Count	
I	491,520	
Iron ARRAMARAMARA chromium	122,880	
	30,720	
	7,680	
Sep 11/22	Sep 11/22 (for 1 ml)	
Non-ferrous Metals	Sep 11/22 1,920 480 480 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120 120	
copper	120 -	_
- monovous till	30	
	8 Bibrese mal	
722		
Sep 11/22	25/11/22 0	
Viscosity @ 40°C	⁴ μ 6μ 14μ Acid Number	21μ 38μ
Severe	Blassomal	
Abnormal	£0.72	
Abnormal Base Abnormal	₩ 0.48	
Severe	\$\begin{align*} \begin{align*} \begi	
Sep 11/22 -	Sep 11/22 +	





Certificate L2367

Laboratory Sample No. Lab Number

Unique Number

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : KCP33285 : 05639078

: 10128608

Received Diagnosed

: 12 Sep 2022 : 14 Sep 2022

Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: KF, PrtCount)

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Contact: Service Manager

TAPEMATION MACHINING INC

T: F:

13 JANIS WAY

USA 95066

SCOTTS VALLEY, CA