

PROBLEM SUMMARY


Sample Rating Trend

VISCOSITY

Machine Id KAESER SFC 315 4040503 (S/N 1165)


Compressor

KAESER SIGMA (OEM) FG-460 (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	NORMAL	ABNORMAL		
Visc @ 40°C	cSt	ASTM D445	46	△ 53.6	50.7	49.9		

Customer Id: SEDMOU Sample No.: KCP49273 Lab Number: 05644273 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

29 Jul 2022 Diag: Doug Bogart

NORMAL



No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



30 Jun 2022 Diag: Angela Borella

ISO



We recommend you service the filters on this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

25 May 2022 Diag: Angela Borella

ISO



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.





OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

KAESER SFC 315 4040503 (S/N 1165)

Component

Compressor

KAESER SIGMA (OEM) FG-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable.


Fluid Condition


The oil viscosity is higher than normal. The AN level is acceptable for this fluid.

v/2015 Smp2018 Oct2019 Mar2020 Smp2020 Apr2021 Smp2021 Mar2022						
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP49273	KCP48383	KCP51951
Sample Date				07 Sep 2022	29 Jul 2022	30 Jun 2022
Machine Age	hrs			59739	59059	58661
Oil Age	hrs			6255	5575	5177
Oil Changed				Not Changd	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	2	2	3
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	<1	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	0	<1	0
Aluminum	ppm	ASTM D5185m	>10	3	4	2
Lead	ppm	ASTM D5185m	>10	0	0	<1
Copper	ppm	ASTM D5185m	>50	<1	2	2
Tin	ppm	ASTM D5185m	>10	0	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m		0	<1	0
Barium	ppm	ASTM D5185m		1	0	2
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		0	0	<1
Calcium	ppm	ASTM D5185m		0	0	<1
Phosphorus	ppm	ASTM D5185m	500	29	18	39
Zinc	ppm	ASTM D5185m		0	0	4
Sulfur	ppm	ASTM D5185m		215	281	548
CONTAMINANTS	,	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	0	<1	<1
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	0	0	<1
Water	%	ASTM D6304	>0.05	0.004	0.001	0.006
ppm Water	ppm	ASTM D6304	>500	46.8	9.9	69.3
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4µm		ASTM D7647		2873	831	3631
Particles >6µm		ASTM D7647	>1300	399	292	1114
Particles >14µm		ASTM D7647	>80	9	50	<u>^</u> 211
Particles >21µm		ASTM D7647	>20	2	12	<u>\$\times\$</u> 92
Particles >38µm		ASTM D7647	>4	1	1	<u>^</u> 7
Particles >71μm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>/17/13	19/16/10	17/15/13	△ 19/17/15
FLUID DEGRADA	TION	method	limit/base	current	history 1	history 2
Acid Number (AN)	mg KOH/g	ASTM D8045	1.5	1.42	0.61	0.60




OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	TES	method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	46	△ 53.6	50.7	49.9
SAMPLE IMAGES	3	method	limit/base	current	history 1	history 2
Color						
Bottom						







Laboratory Sample No. Lab Number

Unique Number : 10138812

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : KCP49273 : 05644273

Received

: 16 Sep 2022 Diagnosed : 21 Sep 2022 Diagnostician : Jonathan Hester

Test Package : IND 2 (Additional Tests: KF, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

SEDA NORTH AMERICA INC

12501 GLOBE DR MOUNT PLEASANT, WI USA 53177

Contact:

T: F:

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: ? ? - SEDMOU