

PROBLEM SUMMARY

VIS DEBRIS

KAESER SK 18 1428433 (S/N 184521)

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

Sample Rating Trend

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC 1	TEST RE	SULTS			
Sample Status				ABNORMAL	
Debris	scalar	*Visual	NONE	▲ LIGHT	

Customer Id: SUNCAMCA Sample No.: KCP30908 Lab Number: 05648956 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Change Fluid			?	Oil and filter change at the time of sampling has been noted.	
Change Filter			?	Oil and filter change at the time of sampling has been noted.	
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.	



OIL ANALYSIS REPORT

Sample Rating Trend

VIS DEBRIS

KAESER SK 18 1428433 (S/N 184521)

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

Light concentration of visible dirt/debris present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP30908		
Sample Date				21 Sep 2022		
Machine Age	hrs			8661		
Oil Age	hrs			8000		
Oil Changed	1110			Changed		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	1		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>3	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m	>10	4		
Lead	ppm	ASTM D5185m	>10	<1		
Copper	ppm	ASTM D5185m	>50	5		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m	0	0		
Barium	ppm	ASTM D5185m	90	0		
Molybdenum	ppm	ASTM D5185m	0	0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	100	31		
Calcium	ppm	ASTM D5185m	0	3		
Phosphorus	ppm	ASTM D5185m	0	40		
Zinc	ppm	ASTM D5185m	0	104		
Sulfur	ppm	ASTM D5185m	23500	21072		
CONTAMINANTS		method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	3		
Sodium	ppm	ASTM D5185m		8		
Potassium	ppm	ASTM D5185m	>20	<1		
Water	%	ASTM D6304	>0.05	0.020		
ppm Water	ppm	ASTM D6304	>500	201.3		

Acid Number (AN)

mg KOH/g ASTM D8045 1.0

0.39




OIL ANALYSIS REPORT




VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	MODER		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	▲ LIGHT		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.05	NEG		
Free Water	scalar	*Visual		NEG		
FLUID PROPERT	IES	method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	45	45.0		
SAMPLE IMAGES	3	method	limit/base	current	history 1	history 2


Color	no image	no image
Bottom	no image	no image

GRAPHS



	Non-ferrous Metals
- 1	T
	copper
	************* lead
Ε	- tin
mdd	
	1
) -
	72
	Sep 2 1/22
	s s
	\(\(\text{\text{\$1}} =\text{\$1\$}\) \(\text{\$2\$} \) \(\text{\$4000}\)









Laboratory Sample No. Lab Number Unique Number : 10143495

: KCP30908 : 05648956

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

Received Diagnosed

: 22 Sep 2022 : 26 Sep 2022

Diagnostician : Jonathan Hester

Test Package: IND 2 (Additional Tests: KF, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

SUNSTONE CONSTRUCTION

176 GILMAN AVE CAMPBELL, CA USA 95008

Contact: Service Manager

T: F: