



# SAMPLE SUBMISSION FORM

## Oil Analysis Laboratories

501 Madison Avenue C8-1175 Appleby Line  
 Cary, NC 27513 Burlington, ON L7L 5H9  
 USA CANADA  
 1-800-237-1369 1-800-268-2131  
 (919) 379-4102 (905) 569-8600  
 Fax (919) 379-4050 Fax (905) 569-8605

WEARCHECK sample kits will be replaced with unused kits if defective in manufacture, labeling, or packaging, or if lost by us or any associate company even though by negligence or other fault.

WEARCHECK shall not be liable or responsible for the future performance or failure of any engine, piece of equipment or material involved in any test or sample. The Company makes no warranties, representations, or guaranties with respect to the performance of any such engine, piece of equipment, or material.

**NOTE 1:** For sample identification, please ensure that you either print labels and place on the sample bottle or that you label the sample cap with the reference number (\*Label) shown below.

**NOTE 2:** Please attach 5 Sample Information Forms (SIFs) as proof of payment for these analysis.

**Shipping Info**

Shipped Via: Purolator  
 Tracking Number: 15389148576  
 Shipped On: 10/16/2023  
 Submitted By: BILL BUTLER [Oil Filtration Solutions Ltd.]

## SAMPLING INSTRUCTIONS AND PRECAUTIONS

For best results we suggest the following precautions when taking the sample.

**INSTRUCTIONS FOR TAKING SAMPLE** - the SAMPLE should not be taken MORE THAN 30 MINUTES after shutdown, and the oil should have been in service for at least 10 hours or 500 miles, before the oil can accurately reflect wear conditions.  
**AVOID CONTAMINATION OF THE SAMPLE** - Clean around the drain plug before draining. Remove the drain, and when about half the oil has run out, catch the sample by inserting the bottle into the oil stream. The bottle should be at least 3/4 filled. Do not remove the bottle cap until you are ready to take the sample, and recap the bottle immediately after filling. Take care not to confuse samples from different units.  
 Or, remove sample with a suction pump by inserting the siphon tube down the dipstick tube or into the sump/reservoir. The siphon tube must be clean by either replacement or rinsing with a solvent and drying. Do not rinse with gasoline or diesel fuel.  
 Or, Engines with sample ports (i.e. gauge plugs, probalizer mini-plugs), follow the specific instructions pertaining to the sampling device purchased.

## Oil Filtration Solutions Ltd.

	*Label : 405704	Area	NAVIGATOR FISHERIES LTD	Machine Age	: 1236.0
	Sample Number : OF0000887	Machine Id	65FT FISHING VESEL MV ELITE VOYAGER	Fluid Age	: 525.0
	Test Package : MOB 2	Component	KUBOTA V2203 7NW8336 1 Genset	Filter Age	: 525.0
	Sample Date : 10/15/2023	Fluid	DIESEL ENGINE OIL SAE 15W40 (4 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd
	*Label : 405705	Area	NAVIGATOR FISHERIES LTD	Machine Age	: 2671.0
	Sample Number : OF0000886	Machine Id	65FT FISHING VESEL MV ELITE VOYAGER	Fluid Age	: 103.0
	Test Package : MOB 2	Component	CUMMINS 4BB.9-D(M) 46189212 2 Genset	Filter Age	: 103.0
	Sample Date : 10/15/2023	Fluid	APRIL SUPERFLO GOLD K 15W40 (16 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd
	*Label : 405706	Area	NAVIGATOR FISHERIES LTD	Machine Age	: 5065.0
	Sample Number : OF0000883	Machine Id	65FT FISHING VESEL MV ELITE VOYAGER	Fluid Age	: 487.0
	Test Package : MOB 2	Component	MVEVHS Hydraulic System	Filter Age	: 487.0
	Sample Date : 10/15/2023	Fluid	AW HYDRAULIC OIL ISO 32 (2000 LTR)	Fluid Maintenance	: Changed
				Filter Maintenance	: Changed
	*Label : 405707	Area	NAVIGATOR FISHERIES LTD	Machine Age	: 25237.0
	Sample Number : OF0000888	Machine Id	65FT FISHING VESEL MV ELITE VOYAGER	Fluid Age	: 487.0
	Test Package : MOB 2	Component	CUMMINS K-19 37207225 Main Engine	Filter Age	: 487.0
	Sample Date : 10/15/2023	Fluid	SHELL ROTELLA T 15W40 (84 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd
	*Label : 405708	Area	NAVIGATOR FISHERIES LTD	Machine Age	: 25327.0
	Sample Number : OF0000882	Machine Id	65FT FISHING VESEL MV ELITE VOYAGER	Fluid Age	: 487.0
	Test Package : MOB 2	Component	ZF W65 20032551 Transmission	Filter Age	: 487.0
	Sample Date : 10/15/2023	Fluid	SHELL ROTELLA T 30 (20 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd