



SAMPLE SUBMISSION FORM

Oil Analysis Laboratories

501 Madison Avenue C8-1175 Appleby Line
 Cary, NC 27513 Burlington, ON L7L 5H9
 USA CANADA
 1-800-237-1369 1-800-268-2131
 (919) 379-4102 (905) 569-8600
 Fax (919) 379-4050 Fax (905) 569-8605

WEARCHECK sample kits will be replaced with unused kits if defective in manufacture, labeling, or packaging, or if lost by us or any associate company even though by negligence or other fault.

WEARCHECK shall not be liable or responsible for the future performance or failure of any engine, piece of equipment or material involved in any test or sample. The Company makes no warranties, representations, or guaranties with respect to the performance of any such engine, piece of equipment, or material.

NOTE 1: For sample identification, please ensure that you either print labels and place on the sample bottle or that you label the sample cap with the reference number (*Label) shown below.

NOTE 2: Please attach 9 Sample Information Forms (SIFs) as proof of payment for these analysis.

Shipping Info

Shipped Via:
 Tracking Number:
 Shipped On:
 Submitted By: BILL BUTLER [Oil Filtration Solutions Ltd.]

SAMPLING INSTRUCTIONS AND PRECAUTIONS

For best results we suggest the following precautions when taking the sample.

INSTRUCTIONS FOR TAKING SAMPLE - the SAMPLE should not be taken MORE THAN 30 MINUTES after shutdown, and the oil should have been in service for at least 10 hours or 500 miles, before the oil can accurately reflect wear conditions. AVOID CONTAMINATION OF THE SAMPLE - Clean around the drain plug before draining. Remove the drain, and when about half the oil has run out, catch the sample by inserting the bottle into the oil stream. The bottle should be at least 3/4 filled. Do not remove the bottle cap until you are ready to take the sample, and recap the bottle immediately after filling. Take care not to confuse samples from different units. Or, remove sample with a suction pump by inserting the siphon tube down the dipstick tube or into the sump/reservoir. The siphon tube must be clean by either replacement or rinsing with a solvent and drying. Do not rinse with gasoline or diesel fuel. Or, Engines with sample ports (i.e. gauge plugs, probalizer mini-plugs), follow the specific instructions pertaining to the sampling device purchased.

Oil Filtration Solutions Ltd.

	*Label : 406607	Area	OLIVIC FISHERIES LTD	Machine Age	: 8341.0
	Sample Number : OF0000713	Machine Id	FISHING VESSEL MV NEWFOUNDLAND MARINER	Fluid Age	: 786.0
	Test Package : MOB 2	Component	Nanni Diesel QM533M60 GDK16070077 1 Genset	Filter Age	: 786.0
	Sample Date : 10/13/2023	Fluid	SHELL ROTELLA T 15W40 (8 LTR)	Fluid Maintenance	: Changed
				Filter Maintenance	: Changed
	*Label : 406608	Area	OLIVIC FISHERIES LTD	Machine Age	: 477.0
	Sample Number : OF0000712	Machine Id	FISHING VESSEL MV NEWFOUNDLAND MARINER	Fluid Age	: 477.0
	Test Package : MOB 2	Component	JOHN DEERE 6068TFM50 CD6068TZ5058 2 Genset	Filter Age	: 227.0
	Sample Date : 10/13/2023	Fluid	SHELL ROTELLA T 15W40 (10 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd
	*Label : 406609	Area	OLIVIC FISHERIES LTD	Machine Age	: 5425.0
	Sample Number : OF0000715	Machine Id	FISHING VESSEL MV NEWFOUNDLAND MARINER	Fluid Age	: 925.0
	Test Package : MOB 2	Component	MVNMHS Hydraulic System	Filter Age	: 150.0
	Sample Date : 10/13/2023	Fluid	AW HYDRAULIC OIL ISO 32 (2000 LTR)	Fluid Maintenance	: Not Changed
				Filter Maintenance	: Changed
	*Label : 406610	Area	OLIVIC FISHERIES LTD	Machine Age	: 14771.0
	Sample Number : OF0000716	Machine Id	FISHING VESSEL MV NEWFOUNDLAND MARINER	Fluid Age	: 1480.0
	Test Package : MOB 2	Component	MITSUBISHI S12A2-Y1MPTA 27481 Main Engine	Filter Age	: 480.0
	Sample Date : 09/28/2023	Fluid	SHELL ROTELLA T 15W40 (144 LTR)	Fluid Maintenance	: Changed
				Filter Maintenance	: Changed
	*Label : 406611	Area	OLIVIC FISHERIES LTD	Machine Age	: 15061.0
	Sample Number : OF0000714	Machine Id	FISHING VESSEL MV NEWFOUNDLAND MARINER	Fluid Age	: 1770.0
	Test Package : MOB 2	Component	TWIN DISC MVNMT Transmission	Filter Age	: 1746.0
	Sample Date : 10/13/2023	Fluid	SHELL ROTELLA T 30 (38 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd
	*Label : 407272	Area	SOUND VENTURES ENTERPRISES LTD	Machine Age	: 13666.0
	Sample Number : OF0000740	Machine Id	FISHING VESSEL MV SOUND VENTURE	Fluid Age	: 771.0
	Test Package : MOB 1	Component	KUBOTA V3800-T 2CQ3287 1 Genset	Filter Age	: 771.0
	Sample Date : 10/17/2023	Fluid	(8 LTR)	Fluid Maintenance	: Changed
				Filter Maintenance	: Changed



*Label : 407273
 Sample Number : OF0000737
 Test Package : MOB 1
 Sample Date : 10/17/2023

Area **SOUND VENTURES ENTERPRISES LTD**
 Machine Id **FISHING VESSEL MV SOUND VENTURE**
 Component Hydraulic System
 Fluid (750 LTR)

Machine Age : 2870.0
 Fluid Age : 2870.0
 Filter Age : 270.0
 Fluid Maintenance : Not Changd
 Filter Maintenance : Changed



*Label : 407274
 Sample Number : OF0000739
 Test Package : MOB 1
 Sample Date : 10/17/2023

Area **SOUND VENTURES ENTERPRISES LTD**
 Machine Id **FISHING VESSEL MV SOUND VENTURE**
 Component CATERPILLAR C-18 TNA05121 Main Engine
 Fluid (84 LTR)

Machine Age : 12965.0
 Fluid Age : 1555.0
 Filter Age : 555.0
 Fluid Maintenance : Changed
 Filter Maintenance : Changed



*Label : 407275
 Sample Number : OF0000738
 Test Package : MOB 1
 Sample Date : 10/17/2023

Area **SOUND VENTURES ENTERPRISES LTD**
 Machine Id **FISHING VESSEL MV SOUND VENTURE**
 Component TWIN DISC MVSVT Transmission
 Fluid (45 LTR)

Machine Age : 13666.0
 Fluid Age : 1555.0
 Filter Age : 555.0
 Fluid Maintenance : Not Changd
 Filter Maintenance : Changed