

SAMPLE SUBMISSION FORM

Oil Analysis Laboratories

501 Madison Avenue Cary, NC 27513

C8-1175 Appleby Line Burlington, ON L7L 5H9 CANADA

USA 1-800-237-1369

1-800-268-2131 (905) 569-8600

(919) 379-4102 Fax (919) 379-4050

Fax (905) 569-8605

NOTE 1: For sample identification, please ensure that you either print labels and place on the sample bottle or that you label the sample cap with the reference number (*Label) shown below.

NOTE 2: Please attach 4 Sample Information Forms (SIFs) as proof of payment for these analysis.

WEARCHECK sample kits will be replaced with unused kits if defective in manufacture, labeling, or packaging, or if lost by us or any associate company even though by negligence or other fault.

WEARCHECK shall not be liable or responsible for the future performance or failure of any engine, piece of equipment or material involved in any test or sample. The Company makes no warranties, representations, or guaranties with respect to the performance of any such engine, piece of equipment, or material

Shipping Info

Shipped Via:

Tracking Number:

Shipped On:

Submitted By: DAVID WARD [HIGH PERFORMANCE LUBRICANTS LLC]

SAMPLING INSTRUCTIONS AND PRECAUTIONS

For best results we suggest the following precautions when taking the sample.

INSTRUCTIONS FOR TAKING SAMPLE - the SAMPLE should not be taken MORE THAN 30 MINUTES after shutdown, and the oil should have been in service for at least 10 hours or 500 miles, before the oil can accurately reflect wear conditions. AVOID CONTAMINATION OF THE SAMPLE - Clean around the drain plug before draining. Remove the drain, and when about half the oil has run out, catch the sample by inserting the bottle into the oil stream. The bottle should be at least 3/4 filled. Do not remove the bottle cap until you are ready to take the sample, and recap the bottle immediately after filling. Take care not to confuse samples from different units,

Or, remove sample with a suction pump by inserting the siphon tube down the dipstick tube or into the sump/reservoir. The siphon tube must be clean by either replacement or rinsing with a solvent and drying. Do not rinse with gasoline or diesel fuel. Or, Engines with sample ports (i.e. gauge plugs, probalizer mini-plugs), follow the specific instructions pertaining to the sampling device purchased.

HIGH PERFORMANCE LUBRICANTS LLC

Machine Age : 444907 *Label Fluid Age Sample Number : HPL0000942 Machine Id 240101 Z-CLOE-435 Filter Age

Test Package : MOB 2 Component New (Unused) Oil Fluid Maintenance : Not Changd Sample Date : 02/01/2024 (--- GAL) Filter Maintenance

: 445169 Machine Age Label Fluid Age 24A0103 FGHT-0055 Sample Number : HPL0000943 Machine Id

Filter Age Test Package : MOB 2 Component New (Unused) Oil Fluid Maintenance : Not Changd Sample Date : 02/02/2024 Fluid (--- GAL) Filter Maintenance

Machine Age Label : 444155 Fluid Age Sample Number : HPL0000935 Machine Id 24A3004 HDMO-720

Filter Age Test Package : MOB 2 Component New (Unused) Oil Fluid Maintenance : Not Changd Sample Date : 01/31/2024 Fluid (--- GAL) **Filter Maintenance**

: 444754 Machine Age Label Fluid Age : HPL0000941 Sample Number Machine Id 24A3007 CL-025 Filter Age

Test Package : MOB 2 Component New (Unused) Oil Fluid Maintenance : Not Changd Sample Date : 02/01/2024 Fluid (--- GAL) Filter Maintenance

TEMP FILE

Machine Age : 12773.0 : 445492 Area **BUCKET TRUCK** Fluid Age : 217.0 : HPL0002291 **FREIGHTLINER V036** Sample Number Machine Id : 217.0 Filter Age : MOB 2 Test Package Component Diesel Engine Fluid Maintenance : Not Changd Sample Date Fluid HIGH PERFORMANCE LUBRICANTS HDMO 15W40 (17 QTS) Filter Maintenance : Not Changd

Transit Id: 444155 to 445492 Page 1 of 1