








**To: TOMMY GRIFFIN**  
 McClung-Logan Virginia LLC  
 4112 HOLLAND BLVD  
 CHESAPEAKE, VA, USA 23323

**Laboratory**  
 WearCheck USA  
 501 Madison Ave.  
 Cary, NC, USA 27513

**FAX ONLY/DO NOT MAIL**

**McClung-Logan Virginia LLC - 2025 COOK DRIVE, SALEM, VA 24153**

<b>Sample No.</b> : VCP302549		Area	<b>[2728]</b>	WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05173508		Machine Id	<b>VOLVO A30G 740136</b>	CONTAMINATION	<b>NORMAL</b>
<b>Test Package</b> : MOB 1		Component	Bogie/Center Axle	FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 18 Jan 2021		Fluid	NOT GIVEN (--- GAL)		
<b>Sample No.</b> : VCP302551		Area	<b>[2728]</b>	WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05173496		Machine Id	<b>VOLVO A30G 740136</b>	CONTAMINATION	<b>NORMAL</b>
<b>Test Package</b> : MOB 1		Component	Diesel Engine	FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 20 Jan 2021		Fluid	DIESEL ENGINE OIL SAE 15W40 (--- GAL)		
<b>Sample No.</b> : VCP302539		Area	<b>[2728]</b>	WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05173509		Machine Id	<b>VOLVO A30G 740136</b>	CONTAMINATION	<b>ABNORMAL</b>
<b>Test Package</b> : MOB 1		Component	Drop Box	FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 18 Jan 2021		Fluid	GEAR OIL SAE 80 (--- GAL)		
<b>Sample No.</b> : VCP302552		Area	<b>[2728]</b>	WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05173506		Machine Id	<b>VOLVO A30G 740136</b>	CONTAMINATION	<b>NORMAL</b>
<b>Test Package</b> : MOB 1		Component	Front Axle	FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 20 Jan 2021		Fluid	NOT GIVEN (--- GAL)		
<b>Sample No.</b> : VCP302541		Area	<b>[2728]</b>	WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05173331		Machine Id	<b>VOLVO A30G 740136</b>	CONTAMINATION	<b>ABNORMAL</b>
<b>Test Package</b> : MOB 2		Component	Hydraulic System	FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 20 Jan 2021		Fluid	NOT GIVEN (--- GAL)		
<b>Sample No.</b> : VCP302550		Area	<b>[2728]</b>	WEAR	<b>NORMAL</b>
<b>Lab Number</b> : 05173505		Machine Id	<b>VOLVO A30G 740136</b>	CONTAMINATION	<b>NORMAL</b>
<b>Test Package</b> : MOB 1		Component	Rear Axle	FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 20 Jan 2021		Fluid	NOT GIVEN (--- GAL)		
<b>Sample No.</b> : VCP302538		Area	<b>[2728]</b>	WEAR	<b>ABNORMAL</b>
<b>Lab Number</b> : 05173512		Machine Id	<b>VOLVO A30G 740136</b>	CONTAMINATION	<b>ABNORMAL</b>
<b>Test Package</b> : MOB 1		Component	Transmission (Auto)	FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 20 Jan 2021		Fluid	DEXRON III (--- GAL)		

*This page left intentionally blank*