

FLUID ANALYSIS REPORTS

To: Tom Hatzioannidis
 GFL Environmental Inc. - S0216
 15 Bermondsey Road
 Toronto, ON, Canada M4B 0A6

GFL Environmental Inc. - S0216 - 15 Bermondsey Road, Toronto, ON M4B 0A6

Sample No. : GFL0017033
Lab Number : 02401852
Test Package : MOB 1
Sampled : 02 Feb 2021

Machine Id **425071**
 Component Hydraulic System
 Fluid AW HYDRAULIC OIL ISO 32 (--- GAL)

WEAR	SEVERE
CONTAMINATION	SEVERE
FLUID CONDITION	ABNORMAL

This page left intentionally blank