




**To: Victoria Verbitska**

GFL Environmental - 200 - Canada Head Office  
100 New Park Place  
Vaughan, ON, Canada L4K 0H9

**GFL Environmental - 778 - Ottawa East - Hauling - 5001 Herbert Drive,, Navan, ON K4B 0G7**

<b>Sample No.</b> : GFL0015030		Machine Id	<b>JOHN DEERE 130G OR384 (S/N 1ff130gxved040675)</b>	CORROSION	<b>NORMAL</b>
<b>Lab Number</b> : 02401973		Component	Coolant	CONTAMINANTS	<b>NORMAL</b>
<b>Test Package</b> : COOL		Fluid	EXTENDED LIFE COOLANT (--- GAL)	COOLANT CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 02 Feb 2021					
<b>Sample No.</b> : GFL0015031		Machine Id	<b>JOHN DEERE 130G OR384 (S/N 1ff130gxved040675)</b>	WEAR	<b>ABNORMAL</b>
<b>Lab Number</b> : 02401966		Component	Swing Drive	CONTAMINATION	<b>SEVERE</b>
<b>Test Package</b> : MOB 1		Fluid	GEAR OIL SAE 80W90 (--- GAL)	FLUID CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 02 Feb 2021					
<b>Sample No.</b> : GFL0015397		Machine Id	<b>JOHN DEERE 724k OR385 (S/N 1dw724kzhcd646695)</b>	CORROSION	<b>NORMAL</b>
<b>Lab Number</b> : 02401974		Component	Coolant	CONTAMINANTS	<b>NORMAL</b>
<b>Test Package</b> : COOL		Fluid	EXTENDED LIFE COOLANT (--- GAL)	COOLANT CONDITION	<b>NORMAL</b>
<b>Sampled</b> : 29 Jan 2021					

*This page left intentionally blank*