

**To: Service Manager**  
 GFL Environmental - Solid Waste - Central  
 , , Canada

**Customer Service Note**

*We are now e-mailing all sample report batches in PDF format. Please provide your e-mail address on this form and return by fax or email.*

E-mail: \_\_\_\_\_

**FAX this page to 905-569-8605**

or

**Send an e-mail to customerservice@wearcheck.com with the subject: GFLCSCENT\_151760**

**GFL Environmental - 246 - 2700 Deziel Dr, Windsor, ON N8W 5H8**

**Sample No.** : GFL0019119  
**Lab Number** : 02402073  
**Test Package** : MOB 1  
**Sampled** : 02 Feb 2021



Machine Id **MACK WD206**  
 Component Diesel Engine  
 Fluid DIESEL ENGINE OIL SAE 15W40 (--- GAL)

WEAR	<b>ABNORMAL</b>
CONTAMINATION	<b>NORMAL</b>
FLUID CONDITION	<b>NORMAL</b>

*This page left intentionally blank*