














To: EDDIE SECO
 E.C. PACE CO.
 1811 HOLLINS RD.
 ROANOKE, VA, USA 24012

Laboratory
 WearCheck USA
 501 Madison Ave.
 Cary, NC, USA 27513

DO NOT MAIL

E.C. PACE CO. - 1811 HOLLINS RD., ROANOKE, VA 24012

Sample No. : WC0534274 Lab Number : 05221109 Test Package : MOB1+ Sampled : 16 Mar 2021		Machine Id Component Fluid	CATERPILLAR 308E EX-011 (S/N JX07782) Diesel Engine MOBIL 15W40 (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL
Sample No. : WC0534271 Lab Number : 05221080 Test Package : MOB 1 Sampled : 16 Mar 2021		Machine Id Component Fluid	CATERPILLAR 308E EX-011 (S/N JX07782) Hydraulic System CAT HYDO (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL
Sample No. : WC0534272 Lab Number : 05221072 Test Package : MOB 1 Sampled : 16 Mar 2021		Machine Id Component Fluid	CATERPILLAR 308E EX-011 (S/N JX07782) Left Final Drive NOT GIVEN (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL
Sample No. : WC0534273 Lab Number : 05221073 Test Package : MOB 1 Sampled : 16 Mar 2021		Machine Id Component Fluid	CATERPILLAR 308E EX-011 (S/N JX07782) Right Final Drive NOT GIVEN (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL ABNORMAL NORMAL
Sample No. : WC0449271 Lab Number : 05221082 Test Package : MOB 1 Sampled : 24 Mar 2021		Machine Id Component Fluid	CATERPILLAR 330DL EX-307 (S/N ONBD00450) Hydraulic System CAT HYDO (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL
Sample No. : WC0449262 Lab Number : 05221114 Test Package : MOB1+ Sampled : 24 Mar 2021		Machine Id Component Fluid	CATERPILLAR 330DL EX-307 (S/N ONBD00450) Rear Diesel Engine MOBIL DELVAC 1300 SUPER15W40 (11 GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL ATTENTION
Sample No. : WC0449268 Lab Number : 05221063 Test Package : MOB 1 Sampled : 24 Mar 2021		Machine Id Component Fluid	CATERPILLAR 330DL EX-307 (S/N ONBD00450) Right Final Drive MOBIL 50W (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	ABNORMAL SEVERE ATTENTION
Sample No. : WC0449270 Lab Number : 05221064 Test Package : MOB 1 Sampled : 24 Mar 2021		Machine Id Component Fluid	CATERPILLAR 330DL EX-307 (S/N ONBD00450) Swing Drive MOBIL 50W (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL

Sample No. : WC0534243				WEAR	NORMAL
Lab Number : 05221111	Machine Id	DR-101		CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 02 Mar 2021	Fluid	MOBIL 15W40 (--- GAL)			
Sample No. : WC0534242				WEAR	NORMAL
Lab Number : 05221081	Machine Id	DR-101		CONTAMINATION	ABNORMAL
Test Package : MOB 1	Component	Hydraulic System		FLUID CONDITION	NORMAL
Sampled : 02 Mar 2021	Fluid	NOT GIVEN (--- GAL)			
Sample No. : WC0534240				WEAR	NORMAL
Lab Number : 05221061	Machine Id	DR-101		CONTAMINATION	SEVERE
Test Package : MOB 1	Component	Left Final Drive		FLUID CONDITION	NORMAL
Sampled : 02 Mar 2021	Fluid	NOT GIVEN (--- GAL)			
Sample No. : WC0534241				WEAR	NORMAL
Lab Number : 05221062	Machine Id	DR-101		CONTAMINATION	ABNORMAL
Test Package : MOB 1	Component	Right Final Drive		FLUID CONDITION	NORMAL
Sampled : 02 Mar 2021	Fluid	NOT GIVEN (--- GAL)			
Sample No. : WC0534270				WEAR	NORMAL
Lab Number : 05221117	Machine Id	EX-312		CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 26 Mar 2021	Fluid	MOBIL 15W40 (--- GAL)			
Sample No. : WC0534307				WEAR	NORMAL
Lab Number : 05221084	Machine Id	FORD TS-702		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Left Hydraulic System		FLUID CONDITION	NORMAL
Sampled : 12 Mar 2021	Fluid	SAE 10W (--- QTS)			
Sample No. : WC0534269				WEAR	NORMAL
Lab Number : 05221066	Machine Id	KOMATSU PC220LC-7 EX-202 (S/N A86797)		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Center Swing Drive		FLUID CONDITION	NORMAL
Sampled : 21 Mar 2021	Fluid	MOBIL MOBILTRANS HD 30 (--- GAL)			
Sample No. : WC0534238				WEAR	NORMAL
Lab Number : 05221115	Machine Id	KOMATSU PC228USLC-3 EX-207 (S/N 40463)		CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 28 Mar 2021	Fluid	MOBIL 15W40 (6 GAL)			
Sample No. : WC0534239				WEAR	ABNORMAL
Lab Number : 05221083	Machine Id	KOMATSU PC228USLC-3 EX-207 (S/N 40463)		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Hydraulic System		FLUID CONDITION	NORMAL
Sampled : 23 Mar 2021	Fluid	MOBIL 10W (--- GAL)			
Sample No. : WC0534268				WEAR	ABNORMAL
Lab Number : 05221068	Machine Id	KOMATSU PC228USLC-3 EX-207 (S/N 40463)		CONTAMINATION	ABNORMAL
Test Package : MOB 1	Component	Left Final Drive		FLUID CONDITION	NORMAL
Sampled : 28 Mar 2021	Fluid	MOBIL MOBILTRANS HD 50 (--- GAL)			
Sample No. : WC0534315				WEAR	ABNORMAL
Lab Number : 05221067	Machine Id	KOMATSU PC228USLC-3 EX-207 (S/N 40463)		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Right Final Drive		FLUID CONDITION	NORMAL
Sampled : 23 Mar 2021	Fluid	MOBIL MOBILTRANS HD 50 (--- GAL)			
Sample No. : WC0534262				WEAR	NORMAL
Lab Number : 05221074	Machine Id	KOMATSU TA-308		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Center Left Final Drive		FLUID CONDITION	NORMAL
Sampled : 08 Mar 2021	Fluid	KOMATSU AXO 80 (--- GAL)			
Sample No. : WC0534264				WEAR	ABNORMAL
Lab Number : 05221108	Machine Id	KOMATSU TA-308		CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 08 Mar 2021	Fluid	DIESEL ENGINE OIL SAE 15W40 (--- GAL)			
Sample No. : WC0534261				WEAR	NORMAL
Lab Number : 05221075	Machine Id	KOMATSU TA-308		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Front Right Final Drive		FLUID CONDITION	NORMAL
Sampled : 08 Mar 2021	Fluid	KOMATSU AXO 80 (--- GAL)			

Sample No. : WC0534259				WEAR	NORMAL
Lab Number : 05221071	Machine Id	KOMATSU TA-308		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Rear Differential		FLUID CONDITION	NORMAL
Sampled : 08 Mar 2021	Fluid	KOMATSU AXO 80 (--- GAL)			
Sample No. : WC0534306				WEAR	NORMAL
Lab Number : 05221060	Machine Id	KOMATSU TA-308		CONTAMINATION	ABNORMAL
Test Package : MOB 1	Component	Rear Right Final Drive		FLUID CONDITION	NORMAL
Sampled : 08 Mar 2021	Fluid	KOMATSU AXO 80 (--- GAL)			
Sample No. : WC0534244				WEAR	NORMAL
Lab Number : 05221110	Machine Id	LW-210		CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 01 Mar 2021	Fluid	MOBIL 15W40 (--- GAL)			
Sample No. : WC0317752				WEAR	NORMAL
Lab Number : 05220979	Machine Id	MACK TD-401		CONTAMINATION	ABNORMAL
Test Package : MOB 1	Component	Transmission		FLUID CONDITION	NORMAL
Sampled : 31 Mar 2021	Fluid	MACK M DRIVE (--- GAL)			
Sample No. : WC0534314				WEAR	NORMAL
Lab Number : 05221118	Machine Id	PWD-103		CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 10 Mar 2021	Fluid	DIESEL ENGINE OIL SAE 15W40 (--- GAL)			
Sample No. : WC0534237				WEAR	NORMAL
Lab Number : 05221113	Machine Id	PWD-104		CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 02 Mar 2021	Fluid	MOBIL 15W40 (--- GAL)			
Sample No. : WC0534309				WEAR	NORMAL
Lab Number : 05220978	Machine Id	TD-109		CONTAMINATION	ABNORMAL
Test Package : MOB 1	Component	Transmission		FLUID CONDITION	NORMAL
Sampled : 29 Mar 2021	Fluid	MERCURON LV (--- GAL)			



This page left intentionally blank