







To: TRENT BROADWELL
 ASCENDUM MACHINERY INC - GARNER
 3561 JONES SAUSAGE ROAD
 GARNER, NC, USA 27529

Laboratory
 WearCheck USA
 501 Madison Ave.
 Cary, NC, USA 27513

DO NOT MAIL PER BRIAN 10/13/10

ASCENDUM MACHINERY - 215 FANNING FIELDS RD, MILLS RIVER, NC 28759

Sample No. : VCP303502 Lab Number : 05220967 Test Package : MOB 1 Sampled : 31 Mar 2021		Machine Id Component Fluid	VOLVO A40G 341577 Bogie/Center Axle NOT GIVEN (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	SEVERE ABNORMAL NORMAL
Sample No. : VCP304913 Lab Number : 05220963 Test Package : MOB 1 Sampled : 31 Mar 2021		Machine Id Component Fluid	VOLVO A40G 341577 Diesel Engine VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3 (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL
Sample No. : VCP304914 Lab Number : 05220969 Test Package : MOB 1 Sampled : 31 Mar 2021		Machine Id Component Fluid	VOLVO A40G 341577 Drop Box NOT GIVEN (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL
Sample No. : VCP303501 Lab Number : 05220968 Test Package : MOB 1 Sampled : 31 Mar 2021		Machine Id Component Fluid	VOLVO A40G 341577 Front Axle NOT GIVEN (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL
Sample No. : VCP304918 Lab Number : 05220858 Test Package : MOB 2 Sampled : 31 Mar 2021		Machine Id Component Fluid	VOLVO A40G 341577 Hydraulic System VOLVO SUPER HYDRAULIC OIL 46 (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL NORMAL NORMAL
Sample No. : VCP304912 Lab Number : 05220966 Test Package : MOB 1 Sampled : 31 Mar 2021		Machine Id Component Fluid	VOLVO A40G 341577 Rear Axle NOT GIVEN (--- GAL)	WEAR CONTAMINATION FLUID CONDITION	NORMAL ABNORMAL NORMAL

This page left intentionally blank