

To: JERRY ASHLEY
 JERRY F ASHLEY
 34687 US ROUTE 11
 PHILADELPHIA, NY, USA 13673

Laboratory
 WearCheck USA
 501 Madison Ave.
 Cary, NC, USA 27513

JERRY F ASHLEY - 34687 US ROUTE 11, PHILADELPHIA, NY 13673

Sample No.	: LF0000076				
Lab Number	: 05223294	Machine Id	VOLVO VNL 07 (S/N 79168140)	WEAR	NORMAL
Test Package	: MOB 1	Component	Diesel Engine	CONTAMINATION	NORMAL
Sampled	: 29 Mar 2021	Fluid	SHELL ROTELLA T 15W40 (11 GAL)	FLUID CONDITION	NORMAL

This page left intentionally blank