

To: JOHN BUCKNER
 ALTA CONSTRUCTION EQUIPMENT LLC
 G-3283 S. DORT HIGHWAY
 BURTON, MI, USA 48529

Laboratory
 WearCheck USA
 501 Madison Ave.
 Cary, NC, USA 27513

ALTA CONSTRUCTION EQUIPMENT LLC - G-3283 S. DORT HIGHWAY, BURTON, MI 48529

Sample No. : VCP303529	Area	[SWO521867]	WEAR	NORMAL
Lab Number : 05221901	Machine Id	VOLVO L260H 1143	CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Diesel Engine	FLUID CONDITION	NORMAL
Sampled : 29 Mar 2021	Fluid	VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3 (--- GAL)		

Sample No. : VCP303531	Area	[SWO580737 MI SUGAR]	WEAR	NORMAL
Lab Number : 05221979	Machine Id	VOLVO L180 4058	CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Transmission (Auto)	FLUID CONDITION	NORMAL
Sampled : 26 Mar 2021	Fluid	VOLVO AUTOMATIC TRANSMISSION FLUID (--- GAL)		



This page left intentionally blank