

To: Matt Hanna
GFL Environmental - 656 -Culpeper Hauling
15490 Montanus Drive
Culpeper, VA, USA 22701

Laboratory
WearCheck USA
501 Madison Ave.
Cary, NC, USA 27513

GFL Environmental - 656 -Culpeper Hauling - 15490 Montanus Drive, Culpeper, VA 22701

Sample No. : GFL0019780	Machine Id	12019	WEAR	NORMAL
Lab Number : 05221116	Component	Diesel Engine	CONTAMINATION	NORMAL
Test Package : MOB1+	Fluid	CONOCO PHILLIPS GUARDOL ECT 15W40 (--- LTR)	FLUID CONDITION	NORMAL
Sampled : 30 Mar 2021				

This page left intentionally blank