

To: RITA GARCIA
 McLane Company - High Plains - 600HP
 1717 East Loop 289
 LUBBOCK, TX, USA 79403

Laboratory
 WearCheck USA
 501 Madison Ave.
 Cary, NC, USA 27513

McLane Company - High Plains - 600HP - 1717 East Loop 289, LUBBOCK, TX 79403

Sample No. : PCA0038990	Area	(P162784) 600HP	WEAR	NORMAL
Lab Number : 05233149	Machine Id	530588 [600HP]	CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine	FLUID CONDITION	ATTENTION
Sampled : 02 Apr 2021	Fluid	MOBIL 1 SAE 10W30 (--- GAL)		
<hr/>				
Sample No. : PCA0038994	Area	(P62512) 600HP	WEAR	NORMAL
Lab Number : 05233154	Machine Id	530342 [600HP]	CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine	FLUID CONDITION	ATTENTION
Sampled : 14 Apr 2021	Fluid	MOBIL 1 SAE 10W30 (--- GAL)		
<hr/>				
Sample No. : PCA0038989	Area	(T461278) 600HP	WEAR	NORMAL
Lab Number : 05233155	Machine Id	530847 [600HP]	CONTAMINATION	NORMAL
Test Package : MOB1+	Component	Diesel Engine	FLUID CONDITION	NORMAL
Sampled : 31 Mar 2021	Fluid	PETRO CANADA DURON SHP 10W30 (--- GAL)		

This page left intentionally blank