

To: PAUL FLOOD
 MAKO MARINE
 117 HUDSON AVE
 FREEPORT, NY, USA 11520

Laboratory
 WearCheck USA
 501 Madison Ave.
 Cary, NC, USA 27513

MAKO MARINE - 117 HUDSON AVE, FREEPORT, NY 11520

Sample No. : VPA026970				WEAR	NORMAL
Lab Number : 05235177	Machine Id	VOLVO PENTA A355841		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Starboard Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 16 Apr 2021	Fluid	NOT GIVEN (--- GAL)			
<hr/>					
Sample No. : VPA026971				WEAR	NORMAL
Lab Number : 05235178	Machine Id	VOLVO PENTA A355842		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Port Diesel Engine		FLUID CONDITION	NORMAL
Sampled : 16 Apr 2021	Fluid	NOT GIVEN (--- GAL)			
<hr/>					
Sample No. : VPA037910				WEAR	NORMAL
Lab Number : 05235176	Machine Id	WESTERBEKE 1767901		CONTAMINATION	NORMAL
Test Package : MOB 1	Component	Genset		FLUID CONDITION	NORMAL
Sampled : 16 Apr 2021	Fluid	DIESEL ENGINE OIL SAE 40 (--- GAL)			

This page left intentionally blank