

To: S WHITEWOOD
FCS CONSTRUCTION LLC
PO BOX 190829
DALLAS, TX, USA 75219

Laboratory
WearCheck USA
501 Madison Ave.
Cary, NC, USA 27513

FCS CONSTRUCTION LLC - PO BOX 190829, DALLAS, TX 75219

Sample No. : VCP298895
Lab Number : 05235192
Test Package : MOB 1
Sampled : 15 Apr 2021



Area [127009]
Machine Id VOLVO A40G 352175
Component Diesel Engine
Fluid NOT GIVEN (--- GAL)

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

This page left intentionally blank