



C8-1175 Appleby Line
Burlington, ON, Canada L7L 5H9

FLUID ANALYSIS REPORTS

Standard 9 x 5-3/4

To: Patrick Giunta
ROCKCLIFFE FLYING CLUB
1495 SIR GEORGE-ETIENNE CARTIER PARKWAY MAINTENANCE
OTTAWA, ON, Canada K1K 4Y5

ROCKCLIFFE FLYING CLUB - 1495 SIR GEORGE-ETIENNE, CARTIER PARKWAY MAINTENANCE, OTTAWA, ON K1K 4Y5

Sample No. : WC0544846	Area	(C-GDEF)	WEAR	NORMAL
Lab Number : 02417984	Machine Id	[C-GDEF] DIAMOND DA20-CI 650434	CONTAMINATION	NORMAL
Test Package : AVI 1	Component	Piston Aircraft Engine	FLUID CONDITION	NORMAL
Sampled : 10 Mar 2021	Fluid	SHELL AEROSHELL W 15W50 MGR (6 QTS)		
Sample No. : WC0578508	Area	(C-GMME)	WEAR	NORMAL
Lab Number : 02417985	Machine Id	[C-GMME] CESSNA 172M L-30769-27A	CONTAMINATION	NORMAL
Test Package : AVI 1	Component	Piston Aircraft Engine	FLUID CONDITION	NORMAL
Sampled : 20 Apr 2021	Fluid	SHELL AEROSHELL W 15W50 MGR (8 QTS)		
Sample No. : WC0578510	Area	(C-GYWN)	WEAR	NORMAL
Lab Number : 02417983	Machine Id	[C-GYWN] CESSNA C172N L-6371-76T	CONTAMINATION	NORMAL
Test Package : AVI 1	Component	Front Piston Aircraft Engine	FLUID CONDITION	NORMAL
Sampled : 05 Apr 2021	Fluid	SHELL AEROSHELL W 15W50 MGR (2 GAL)		

This page left intentionally blank