

FLUID ANALYSIS REPORTS

To: Victoria Verbitska
 GFL Environmental - 200 - Canada Head Office
 100 New Park Place
 Vaughan, ON, Canada L4K 0H9

GFL Environmental - 737 - Hauling - Solid Waste - 6205 Boul. Wilfrid Hamel,, Quebec City, QC G2E 5G8

Sample No. : PC0040868					
Lab Number : 02417554	Machine Id	810026		WEAR	NORMAL
Test Package : MOB 2	Component	Diesel Engine		CONTAMINATION	NORMAL
Sampled : 08 Apr 2021	Fluid	DIESEL ENGINE OIL SAE 15W40 (--- GAL)		FLUID CONDITION	NORMAL

This page left intentionally blank