

FLUID ANALYSIS REPORTS

To: Victoria Verbitska
 GFL Environmental - 200 - Canada Head Office
 100 New Park Place
 Vaughan, ON, Canada L4K 0H9

GFL Environmental - 225 - COT(D2) - 20 Brydon Drive, Etobicoke, ON M9W 5R6

Sample No. : GFL0022725									
Lab Number : 02418237	Machine Id	0593						WEAR	NORMAL
Test Package : MOB 1	Component	Diesel Engine						CONTAMINATION	NORMAL
Sampled : 27 Apr 2021	Fluid	DIESEL ENGINE OIL SAE 40 (--- GAL)						FLUID CONDITION	NORMAL

This page left intentionally blank