

# MACHINE HEALTH REPORT

# LIEBHERR


## CONSTRUCTION EQUIPMENT




**LIEBHERR 083538-1253**

### Machine Health: 6.8

As of Date: 10/24/2019 @ .0 hrs



#### Hydraulic System



**Front Differential**

**NORMAL**


**Front Left Wheel Hub**

**NORMAL**


**Front Right Wheel Hub**

**NORMAL**

#### Swing Drive



#### Transmission (Manual)



**Rear Left Wheel Hub**

**NORMAL**

**Rear Right Wheel Hub**

**NORMAL**

**Diesel Engine**

**NORMAL**

**Rear Differential**

**NORMAL**