

MACHINE HEALTH REPORT



LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 083538-1253

Machine Health: 6.8



Front Differential



NORMAL

Front Left Wheel Hub

NORMAL

Front Right Wheel Hub

NORMAL



Rear Left Wheel Hub

NORMAL

Rear Right Wheel Hub

NORMAL

Diesel Engine

NORMAL

Rear Differential

NORMAL