

MACHINE HEALTH REPORT

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR L550 038127-1287

Machine Health: 6.8

As of Date: 12/04/2018 @ 8869.0 hrs



Hydraulic System

NORMAL

Front Differential

WEAR

Ferrous Alloys

Sample No. : LH-MC96950
Sample Date : 08/02/2018

Front Left Wheel Hub

WEAR

Ferrous Alloys


Sample No. : LH-MC124639
Sample Date : 12/04/2018

Front Right Wheel Hub

DIRT

Ferrous Alloys

Sample No. : LH-MC124692
Sample Date : 12/04/2018



Splitter Box

NORMAL

Transmission (Automatic)

NORMAL

Rear Left Wheel Hub

NORMAL

Rear Right Wheel Hub

NORMAL

Diesel Engine

NORMAL

Rear Differential

NORMAL