WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL NORMAL



LIEBHERR LH40M 156305-1215

Component Front Right Wheel Hub GEAR OIL SAE 80W90 (GAL							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.	Sample Number		Client Info		LH0278471		
	Sample Date		Client Info		20 Feb 2024		
	Machine Age	hrs	Client Info		536		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		None		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>650	44		
	Chromium	ppm	ASTM D5185(m)		<1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185(m)	>4	0		
	Titanium	ppm	ASTM D5185(m)	>4	0		
	Silver	ppm	ASTM D5185(m)		0		
	Aluminum	ppm	ASTM D5185(m)	>25	2		
	Lead	ppm	ASTM D5185(m)	>4	1		
	Copper	ppm	ASTM D5185(m)	>60	37		
	Tin	ppm	ASTM D5185(m)	>4	0		
	Vanadium	ppm	ASTM D5185(m)		0		
	White Metal	scalar	Visual*	NONE	LIGHT		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>75	9		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	2		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	NONE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)	>170	5		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)	400	4		
	Barium	ppm	ASTM D5185(m)	200	0		
	Molybdenum	ppm	ASTM D5185(m)	12	<1		
	Manganese	ppm	ASTM D5185(m)		3		
	Magnesium	ppm	ASTM D5185(m)		2		
	Calcium	ppm	ASTM D5185(m)		135		
	Phosphorus	ppm	ASTM D5185(m)		1449		
	Zinc	ppm	ASTM D5185(m)		45		
	Sulfur	ppm	ASTM D5185(m)	22500	18107		

Visc @ 40°C

ASTM D7279(m) 143

140





ISO 17025:2017
Accredited
Laboratory

 Laboratory
 : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

 Sample No.
 : LH0278471
 Received
 : 22 Feb 2024

 Lab Number
 : 02617506
 Tested
 : 22 Feb 2024

7025:2017 Lab Number : 02617506 Tested : 22 Feb 2024
Credited Unique Number : 5734616 Diagnosed : 22 Feb 2024 - Wes Davis
Test Package : MOB 1

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Urban Mine
72 Rothwell Rd.
Winnipeg, MB
CA R3P 2H7
Contact: SERVICE

T: (204)774-0192 F: