

OIL ANALYSIS REPORT

WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL


(YRL) PERIMETER AVIATION [53023]

[YRL] FAIRCHILD METRO 23 SA227AC P-44168C (S/N CC-841B)

1 Jet Turbine

EASTMAN TURBO OIL 2380 (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		GT56551	GT57496	GT54785
	Sample Date		Client Info		21 Feb 2024	20 Dec 2023	13 Nov 2023
	Machine Age	hrs	Client Info		0	0	0
	Oil Age	hrs	Client Info		36	845	755
	Filter Age	hrs	Client Info		85	90	92
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status						
WEAR	Water		WC Method	>0.1	NEG	NEG	NEG
CONTAMINATION	Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.71	0.80	0.89
	Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.7		







Laboratory Sample No.

Test Package : G331

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : GT56551 Lab Number : 02619444 Unique Number : 5736554

Received : 01 Mar 2024 **Tested** Diagnosed

Honeywell Engines 111 S. 34th Street, 301 Receiving, Attn: SOAP Program

PHOENIX, AZ US 85034 Contact: GARRETT

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

T: F: (602)365-2676