**WEAR** CONTAMINATION **FLUID CONDITION**  **NORMAL NORMAL NORMAL** 



Machine Id 201108 Component Diesel Engine

PETRO CANADA DURON SHE	100030 ( 0	AAL)					
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		GFL0107886		
	Sample Date		Client Info		20 Feb 2024		
	Machine Age	kms	Client Info		260769		
	Oil Age	kms	Client Info		0		
	Filter Age	kms	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>80	3		
All component wear rates are normal.	Chromium	ppm	ASTM D5185(m)	>5	0		
	Nickel	ppm	ASTM D5185(m)	>2	0		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)	>3	0		
	Aluminum	ppm	ASTM D5185(m)	>30	1		
	Lead	ppm	ASTM D5185(m)	>30	0		
	Copper	ppm	ASTM D5185(m)	>150	<1		
	Tin	ppm	ASTM D5185(m)	>5	0		
	Vanadium	ppm	ASTM D5185(m)		0		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>20	3		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	0		
	Fuel		WC Method	>5	<1.0		
	Water		WC Method	>0.2	NEG		
	Glycol		WC Method		NEG		
	Soot %	%	ASTM D7844*	>3	0		
	Nitration	Abs/cm	ASTM D7624*	>20	5.8		
	Sulfation	Abs/.1mm	ASTM D7415*	>30	18.1		
	Emulsified Water	scalar	Visual*	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)	2	11		
	Barium	ppm	ASTM D5185(m)	0	0		
	Molybdenum	ppm	ASTM D5185(m)	50	59		
	Manganese	ppm	ASTM D5185(m)	0	0		
	Magnesium	ppm	ASTM D5185(m)	950	946		
	Calcium	ppm	ASTM D5185(m)	1050	1071		
	Phosphorus	ppm	ASTM D5185(m)	995	1010		
	Zinc	ppm	ASTM D5185(m)	1180	1150		
	Sulfur	ppm	ASTM D5185(m)	2600	2773		
	Oxidation	Abs/.1mm	ASTM D7414*	>25	14.2		
	Visc @ 100°C	cSt	ASTM D7279(m)	12.00	11.4		





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: GFL0107886 Lab Number : 02619903 Unique Number : 5737013 Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 310 - Winnipeg Received : 05 Mar 2024 : 05 Mar 2024 **Tested** 

: 05 Mar 2024 - Wes Davis Diagnosed

#360 - 555 Hervo Street, Winnipeg, MB CA R3T 3L6 Contact: Joshua Lourenco jlourenco@gflenv.com

T: (204)987-9600

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

Report Id: GFL310 [WCAMIS] 02619903 (Generated: 03/05/2024 12:44:53) Rev: 1