



# OIL ANALYSIS REPORT

WEAR	UNKNOWN
CONTAMINATION	UNKNOWN
FLUID CONDITION	UNKNOWN

Area

**[53154]**

Machine Id

**DHC-37 P-57139 (S/N 404)**

Component

**Jet Turbine**

Fluid

**BP TURBO OIL 2380 (--- LTR)**

## RECOMMENDATION







Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>GT57645</b>	---	---
Sample Date		Client Info		<b>18 Mar 2024</b>	---	---
Machine Age	hrs	Client Info		<b>0</b>	---	---
Oil Age	hrs	Client Info		<b>653</b>	---	---
Filter Age	hrs	Client Info		<b>94</b>	---	---
Oil Changed		Client Info		<b>N/A</b>	---	---
Filter Changed		Client Info		<b>N/A</b>	---	---
Sample Status				<b>---</b>	---	---

## WEAR

Water		WC Method	>0.1	<b>NEG</b>	---	---
-------	--	-----------	------	------------	-----	-----

## CONTAMINATION

Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	<b>0.85</b>	---	---
------------------	----------	------------	------	-------------	-----	-----



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : GT57645  
**Lab Number** : 02627557  
**Unique Number** : 5760689  
**Test Package** : G331

**Received** : 08 Apr 2024  
**Tested** :  
**Diagnosed** :

**Honeywell Engines**  
 111 S. 34th Street, 301 Receiving, Attn: SOAP Program  
 PHOENIX, AZ  
 US 85034  
 Contact: GARRETT

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.

T:  
 F: (602)365-2676