

OIL ANALYSIS REPORT

WEAR CONTAMINATION FLUID CONDITION

UNKNOWN UNKNOWN

Area


CONAIR GROUP INC [53164]

ROCKWELL TC690A P-33046C (S/N 11134)

2 Jet Turbine

BP TURBO OIL 2380 (--- GAL)

IMENDATION							
/14	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		GT57208	GT57099	GT55583
	Sample Date		Client Info		09 Apr 2024	26 Sep 2023	13 Jul 2023
	Machine Age	hrs	Client Info		0	0	0
	Oil Age	hrs	Client Info		160	142	84
	Filter Age	hrs	Client Info		18	58	84
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status						
	Iron	ppm	ASTM D5185(m)	>8	<1	<1	<1
	Chromium	ppm	ASTM D5185(m)	>2	0	0	0
	Nickel	ppm	ASTM D5185(m)	>2	0	0	0
	Silver	ppm	ASTM D5185(m)	>2	0	0	0
	Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	<1
	Lead	ppm	ASTM D5185(m)	>3	<1	<1	<1
	Copper	ppm	ASTM D5185(m)	>3	<1	<1	<1
	Water		WC Method	>0.1	NEG	NEG	NEG
	Magnesium	ppm	ASTM D5185(m)	0	0	0	0
	Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.50	0.52	0.52
	Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.8		







Laboratory Sample No.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : GT57208 Lab Number : 02628320

Unique Number : 5761452

Received : 11 Apr 2024 Tested

Diagnosed

Honeywell Engines 111 S. 34th Street, 301 Receiving, Attn: SOAP Program

PHOENIX, AZ US 85034 Contact: GARRETT

Test Package: G331 (Additional Tests: ICP) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (602)365-2676

T: