## Honeywell


**OIL ANALYSIS REPORT** 

## Area (LNS) THUNDER AIRLINES [53170] Machine Id [LNS] MITSUBISHI MU-2 P-38328 (S/N 1550SA)

Jet Turbine

## SHELL AEROSHELL 500 (--- GAL)

ON Test UOM Method Limit/Abn Current History1 History2								
		Test	UOM	Method	Limit/Abn	Current	History1	History2
		Sample Number		Client Info		GT57453	GT54422	GT52558
		Sample Date		Client Info		11 Apr 2024	16 Feb 2022	16 Mar 2020
		Machine Age	hrs	Client Info		0	0	0
		Oil Age	hrs	Client Info		138	579	386
		Filter Age	hrs	Client Info		138	142	136
		Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A	
		Sample Status						
		Iron	ppm	ASTM D5185(m)	>8	<1		
		Chromium	ppm	ASTM D5185(m)	>2	0		
	Nickel	ppm	ASTM D5185(m)	>2	0			
		Silver	ppm	ASTM D5185(m)	>2	0		
		Aluminum	ppm	ASTM D5185(m)	>2	<1		
		Lead	ppm	ASTM D5185(m)	>3	<1		
		Copper	ppm	ASTM D5185(m)	>3	<1		
		Water		WC Method	>0.1	NEG	NEG	NEG
		Magnesium	ppm	ASTM D5185(m)	0	<1		
		Acid Number (AN)	mg KOH/g	ASTM D974*	0.11	0.09	0.16	0.125
		Visc @ 40°C	cSt	ASTM D7279(m)	25.3	)	26.7	



Lab Number : 02629096 Tested PHOENIX, AZ ISO 17025:2017 Accredited Laboratory Unique Number : 5762228 US 85034 Diagnosed : Test Package : G331 (Additional Tests: ICP) Contact: GARRETT To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: Validity of results and interpretation are based on the sample and information as supplied. F: (602)365-2676

Contact/Location: GARRETT ? - HONPHO Page 2 of 2