

WEAR CONTAMINATION FLUID CONDITION **NORMAL NORMAL NORMAL**

EAST CRANE

170831

2 Slewing Gearbox

Fluid							
{not provided} (GAL)							
Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		PP	PP	PP
	Sample Date		Client Info		18 Apr 2024	26 Jun 2023	27 Mar 202
	Machine Age	hrs	Client Info		0	0	0
	Oil Age	hrs	Client Info		0	0	0
	Filter Age	hrs	Client Info		0	0	0
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status				NORMAL	NORMAL	NORMAL
WEAR	PQ		ASTM D8184*		0	0	0
All component wear rates are normal.	Iron	ppm	ASTM D5185(m)	>50	6	10	10
	Chromium	ppm	ASTM D5185(m)		0	0	0
	Nickel	ppm	ASTM D5185(m)		0	<1	<1
	Titanium	ppm	ASTM D5185(m)		0	0	<1
	Silver	ppm	ASTM D5185(m)		0	0	0
	Aluminum	ppm	ASTM D5185(m)		<1	1	1
	Lead	ppm	ASTM D5185(m)	>15	0	0	2
	Copper	ppm	ASTM D5185(m)	>10	5	9	8
	Tin	ppm	ASTM D5185(m)	>10	0	<1	<1
	Vanadium	ppm	ASTM D5185(m)		0	0	0
	White Metal	scalar	Visual*	NONE	NONE	VLITE	NONE
	Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>25	<1	4	4
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	2	<1	<1
	Water		WC Method	>0.2	NEG	NEG	NEG
	Silt	scalar	Visual*	NONE	NONE	NONE	NONE
	Debris	scalar	Visual*	NONE	VLITE	NONE	NONE
	Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
	Appearance	scalar	Visual*	NORML	NORML	NORML	NORM
	Odor	scalar	Visual*	NORML	NORML	NORML	NORM
	Emulsified Water	scalar	Visual*	>0.2	NEG	NEG	NEG
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		<1	<1	<1
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.	Boron	ppm	ASTM D5185(m)		274	312	305
	Barium	ppm	ASTM D5185(m)		0	0	0
	Molybdenum	ppm	ASTM D5185(m)		0	0	0
	Manganese	ppm	ASTM D5185(m)		0	0	<1
	Magnesium	ppm	ASTM D5185(m)		14	92	91
	Calcium	ppm	ASTM D5185(m)		1	4	3
	Phosphorus	ppm	ASTM D5185(m)		1326	1433	1504
	Zinc	ppm	ASTM D5185(m)		4	6	5
	Sulfur	ppm	ASTM D5185(m)		22112	22257	23255

Acid Number (AN) mg KOH/g ASTM D974*

ASTM D7279(m)

Visc @ 40°C cSt

Report Id: HIBSTJ [WCAMIS] 02630373 (Generated: 04/22/2024 17:47:12) Rev: 1

105 Contact/Location: Sam Nash - HIBSTJ


2.16

2.11

105

2.26

106





CALA ISO 17025:2017 Accredited Laboratory

Sample No. Lab Number

Laboratory

: PP Unique Number : 5763505

: 02630373

Received **Tested** Diagnosed Test Package : IND 2 (Additional Tests: TAN Man)

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 19 Apr 2024 : 22 Apr 2024

: 22 Apr 2024 - Kevin Marson

HIBERNIA MGMT & DEVELOPMENT CO. LTD SUITE 1000,, 100 NEW GOWER STREET ST.JOHNS, NL

CA A1C 6K3 Contact: Sam Nash samantha.m.nash@exxonmobil.com

F: (709)722-3766

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Contact/Location: Sam Nash - HIBSTJ

T: