**WEAR CONTAMINATION FLUID CONDITION** 

**NORMAL NORMAL NORMAL** 

Machine Id

## **DOOSAN DL580-7**

Hydraulic System

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MOB 2 test kits, this testkit includes Particle Count to determine the ISO cleanliness of the fluid.	Sample Number		Client Info		WC0890752		
	Sample Date		Client Info		18 Apr 2024		
	Machine Age	hrs	Client Info		6400		
	Oil Age	hrs	Client Info		250		
	Filter Age	hrs	Client Info		250		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
VEAD							
VEAR	Iron	ppm	ASTM D5185(m)		2		
All component wear rates are normal.	Chromium	ppm	ASTM D5185(m)		0		
	Nickel	ppm	ASTM D5185(m)	>10	0		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)	40	0		
	Aluminum	ppm	ASTM D5185(m)		<1		
	Lead	ppm	ASTM D5185(m)	>10	0		
	Copper	ppm	ASTM D5185(m)		6		
	Tin Vanadium	ppm	ASTM D5185(m)	>10	0		
		ppm	ASTM D5185(m)	NONE	-		
	White Metal	scalar	Visual*	NONE	NONE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>20	0		
There is no indication of any contamination in the component(unconfirmed).	Potassium	ppm	ASTM D5185(m)	>20	8		
	Water		WC Method	>0.1	NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	NONE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>0.1	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185(m)		2		
	Boron	ppm	ASTM D5185(m)		1		
The condition of the oil is acceptable for the time in service.	Barium	ppm	ASTM D5185(m)		0		
	Molybdenum	ppm	ASTM D5185(m)		0		
	Manganese	ppm	ASTM D5185(m)		0		
	Magnesium	ppm	ASTM D5185(m)		2		
	Calcium	ppm	ASTM D5185(m)		38		
	Phosphorus	ppm	ASTM D5185(m)		332		
	Zinc	ppm	ASTM D5185(m)		403		
	Sulfur	ppm	ASTM D5185(m)		761		
		In In					





CALA
Ture
Acceptable 199011

ISO 17025:2017
Accredited

**Laboratory**: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **Sample No.**: WC0890752 **Received**: 23 Apr 2024

 No. 17025:2017
 Lab Number
 : 02630981
 Tested
 : 23 Apr 2024

 Accredited Laboratory
 Unique Number
 : 5772134
 Diagnosed
 : 23 Apr 2024 - Wes Davis

 Test Package
 : MOB 1

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

C.G. EQUIPMENT

7367 Wellington Rd. 30, Unit A Guelph, ON

CA N0M 2T0 Contact: CG Equipment CG Guelph cory@cgequipment.com

T: (519)826-0550 F: (519)837-2055