



# LIEBHERR

## OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	ATTENTION
FLUID CONDITION	NORMAL



Area  
**(336305)**  
Machine Id  
**LIEBHERR L566 057382-1332**  
Component  
**Hydraulic System**  
Fluid  
**AW HYDRAULIC OIL ISO 46 (--- GAL)**

### RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>LH</b>	LH	LH
Sample Date		Client Info		<b>07 Apr 2024</b>	08 Feb 2024	19 Dec 2023
Machine Age	hrs	Client Info		<b>6500</b>	5965	5600
Oil Age	hrs	Client Info		<b>0</b>	0	0
Filter Age	hrs	Client Info		<b>0</b>	0	0
Oil Changed		Client Info		<b>Not Chngd</b>	Changed	Changed
Filter Changed		Client Info		<b>Not Chngd</b>	N/A	N/A
Sample Status				<b>ATTENTION</b>	ATTENTION	NORMAL

### WEAR

All component wear rates are normal.

Iron	ppm	ASTM D5185(m)	>20	<b>6</b>	6	7
Chromium	ppm	ASTM D5185(m)	>10	<b>2</b>	2	2
Nickel	ppm	ASTM D5185(m)	>10	<b>0</b>	0	<1
Titanium	ppm	ASTM D5185(m)		<b>0</b>	0	0
Silver	ppm	ASTM D5185(m)		<b>0</b>	0	0
Aluminum	ppm	ASTM D5185(m)	>10	<b>&lt;1</b>	<1	<1
Lead	ppm	ASTM D5185(m)	>10	<b>2</b>	2	3
Copper	ppm	ASTM D5185(m)	>75	<b>1</b>	1	1
Tin	ppm	ASTM D5185(m)	>10	<b>0</b>	0	0
Vanadium	ppm	ASTM D5185(m)		<b>0</b>	0	0
White Metal	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE

### CONTAMINATION








There is a light amount of silt (particulates < 14 microns in size) present in the oil.

Silicon	ppm	ASTM D5185(m)	>20	<b>0</b>	<1	<1
Potassium	ppm	ASTM D5185(m)	>20	<b>&lt;1</b>	<1	<1
Water		WC Method	>0.1	<b>NEG</b>	NEG	NEG
Particles >4µm		ASTM D7647	>20000	<b>27875</b>	25295	17627
Particles >6µm		ASTM D7647	>5000	<b>1049</b>	1619	530
Particles >14µm		ASTM D7647	>640	<b>57</b>	95	61
Particles >21µm		ASTM D7647	>160	<b>13</b>	26	15
Particles >38µm		ASTM D7647	>40	<b>1</b>	3	1
Particles >71µm		ASTM D7647	>10	<b>1</b>	0	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<b>22/17/13</b>	22/18/14	21/16/13
Silt	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE
Debris	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	<b>NONE</b>	VLITE	NONE
Appearance	scalar	Visual*	NORML	<b>NORML</b>	NORML	NORML
Odor	scalar	Visual*	NORML	<b>NORML</b>	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	<b>NEG</b>	NEG	NEG

### FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Sodium	ppm	ASTM D5185(m)		<b>&lt;1</b>	0	0
Boron	ppm	ASTM D5185(m)	5	<b>0</b>	0	0
Barium	ppm	ASTM D5185(m)	5	<b>0</b>	0	0
Molybdenum	ppm	ASTM D5185(m)	5	<b>0</b>	0	0
Manganese	ppm	ASTM D5185(m)		<b>0</b>	0	0
Magnesium	ppm	ASTM D5185(m)	25	<b>2</b>	1	1
Calcium	ppm	ASTM D5185(m)	200	<b>129</b>	132	141
Phosphorus	ppm	ASTM D5185(m)	300	<b>575</b>	589	669
Zinc	ppm	ASTM D5185(m)	370	<b>711</b>	716	831
Sulfur	ppm	ASTM D5185(m)	2500	<b>1458</b>	1586	1764
Visc @ 40°C	cSt	ASTM D7279(m)	46	<b>44.0</b>	44.4	44.7



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : LH **Received** : 29 Apr 2024  
**Lab Number** : 02631981 **Tested** : 30 Apr 2024  
**Unique Number** : 5773134 **Diagnosed** : 30 Apr 2024 - Kevin Marson  
**Test Package** : MOB 1 ( Additional Tests: PrtCount )

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.

**CGC DIVISION GYPSUM**  
 7200 RUE NOTRE-DAME EST  
 MONTREAL, QC  
 CA H1N 3L6  
 Contact: YVES CHEVALIER

T: (514)255-4061  
 F: (514)255-6075