



# LIEBHERR

## OIL ANALYSIS REPORT

WEAR	<b>NORMAL</b>
CONTAMINATION	<b>NORMAL</b>
FLUID CONDITION	<b>NORMAL</b>



Area  
**(363878)**

Machine Id  
**LIEBHERR L556 065724-1826**

Component  
**Hydraulic System**

Fluid  
**PETRO CANADA HYDREX XV ALL SEASON HYDRAULIC OIL (--- GAL)**

### RECOMMENDATION

Resample at the next service interval to monitor.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>LH</b>	LH0279062	LH0260823
Sample Date		Client Info		<b>08 Feb 2024</b>	24 Jan 2024	13 Dec 2023
Machine Age	hrs	Client Info		<b>1000</b>	10322	9673
Oil Age	hrs	Client Info		<b>0</b>	0	0
Filter Age	hrs	Client Info		<b>0</b>	0	0
Oil Changed		Client Info		<b>Not Chngd</b>	Not Chngd	Not Chngd
Filter Changed		Client Info		<b>Changed</b>	N/A	N/A
Sample Status				<b>NORMAL</b>	ABNORMAL	ATTENTION

### WEAR

All component wear rates are normal.

Iron	ppm	ASTM D5185(m)	>20	<b>3</b>	6	5
Chromium	ppm	ASTM D5185(m)	>10	<b>&lt;1</b>	<1	<1
Nickel	ppm	ASTM D5185(m)	>10	<b>0</b>	<1	<1
Titanium	ppm	ASTM D5185(m)		<b>0</b>	0	0
Silver	ppm	ASTM D5185(m)		<b>0</b>	0	<1
Aluminum	ppm	ASTM D5185(m)	>10	<b>&lt;1</b>	<1	<1
Lead	ppm	ASTM D5185(m)	>10	<b>0</b>	2	2
Copper	ppm	ASTM D5185(m)	>75	<b>&lt;1</b>	2	2
Tin	ppm	ASTM D5185(m)	>10	<b>0</b>	0	0
Vanadium	ppm	ASTM D5185(m)		<b>0</b>	0	0
White Metal	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE

### CONTAMINATION








The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

Silicon	ppm	ASTM D5185(m)	>20	<b>0</b>	1	1
Potassium	ppm	ASTM D5185(m)	>20	<b>&lt;1</b>	<1	0
Water		WC Method	>0.1	<b>NEG</b>	NEG	NEG
Particles >4µm		ASTM D7647	>20000	<b>12840</b>	▲ 49618	● 22056
Particles >6µm		ASTM D7647	>5000	<b>1381</b>	202	778
Particles >14µm		ASTM D7647	>640	<b>40</b>	8	57
Particles >21µm		ASTM D7647	>160	<b>6</b>	1	12
Particles >38µm		ASTM D7647	>40	<b>1</b>	1	0
Particles >71µm		ASTM D7647	>10	<b>1</b>	0	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<b>21/18/12</b>	▲ 23/15/10	● 22/17/13
Silt	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE
Debris	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	<b>VLITE</b>	NONE	NONE
Appearance	scalar	Visual*	NORML	<b>NORML</b>	NORML	NORML
Odor	scalar	Visual*	NORML	<b>NORML</b>	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	<b>NEG</b>	NEG	NEG

### FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Sodium	ppm	ASTM D5185(m)		<b>&lt;1</b>	0	<1
Boron	ppm	ASTM D5185(m)	0	<b>&lt;1</b>	<1	<1
Barium	ppm	ASTM D5185(m)	0	<b>0</b>	0	<1
Molybdenum	ppm	ASTM D5185(m)	0	<b>0</b>	0	0
Manganese	ppm	ASTM D5185(m)	1	<b>0</b>	0	0
Magnesium	ppm	ASTM D5185(m)	0	<b>2</b>	2	1
Calcium	ppm	ASTM D5185(m)	100	<b>170</b>	235	235
Phosphorus	ppm	ASTM D5185(m)	670	<b>657</b>	630	622
Zinc	ppm	ASTM D5185(m)	850	<b>835</b>	765	790
Sulfur	ppm	ASTM D5185(m)	1600	<b>1671</b>	2156	1756
Visc @ 40°C	cSt	ASTM D7279(m)	47.9	<b>43.9</b>	43.5	43.2



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : LH **Received** : 02 May 2024  
**Lab Number** : 02632802 **Tested** : 03 May 2024  
**Unique Number** : 5773955 **Diagnosed** : 03 May 2024 - Wes Davis  
**Test Package** : MOB 1 ( Additional Tests: PrtCount )

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.

**CGC DIVISION GYPSUM**  
 7200 RUE NOTRE-DAME EST  
 MONTREAL, QC  
 CA H1N 3L6  
 Contact: YVES CHEVALIER

T: (514)255-4061  
 F: (514)255-6075