

OIL ANALYSIS REPORT

WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL

Area


**EDI INC** [53227]

**DORNIER D228 P-39276 (S/N 8088)** 

Jet Turbine

BP TURBO OIL 2380 (--- GAL)

RECOMMENDATION  This is a baseline read out on the submitted cample.	Test	UOM	Mathad		(	1	
This is a baseline road out on the submitted sample			Method	Limit/Abn	Current	History1	History2
This is a baseline read-out on the submitted sample.	Sample Number		Client Info		GT56736	GT55768	GT52988
	Sample Date		Client Info		01 May 2024	29 Sep 2022	19 Jun 2022
	Machine Age	hrs	Client Info		0	0	0
	Oil Age	hrs	Client Info		0	323	720
	Filter Age	hrs	Client Info		100	148	149
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status				ATTENTION		
WEAR	Iron	ppm	ASTM D5185(m)	>8	0	0	0
	Chromium	ppm	ASTM D5185(m)	>2	0	0	0
	Nickel	ppm	ASTM D5185(m)	>2	0	0	0
	Silver	ppm	ASTM D5185(m)	>2	0	0	0
	Aluminum	ppm	ASTM D5185(m)	>2	<u> </u>	0	0
	Lead	ppm	ASTM D5185(m)	>3	0	0	0
	Copper	ppm	ASTM D5185(m)	>3	0	0	0
CONTAMINATION	Water		WC Method	>0.1	NEG	NEG	NEG
FLUID CONDITION	Magnesium	ppm	ASTM D5185(m)	0	<1	<1	0
	Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.84	0.60	0.56
	Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.5		24.5





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : GT56736 Lab Number : 02632961

Unique Number : 5774114 Test Package: G331 (Additional Tests: ICP)

Received **Tested** Diagnosed

: 02 May 2024 : 02 May 2024

: 02 May 2024 - Wes Davis

**Honeywell Engines** 111 S. 34th Street, 301 Receiving, Attn: SOAP Program PHOENIX, AZ

US 85034 Contact: GARRETT

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T: F: (602)365-2676