
**WEAR** CONTAMINATION **FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

[154902] **74950779**Component

Component Diesel Engine

VALVOLINE PREMIUM BLUE EXTREME 5W40	( GAL)						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		CU0022798		
	Sample Date		Client Info		15 Mar 2024		
	Machine Age	hrs	Client Info		8		
	Oil Age	hrs	Client Info		1		
	Filter Age	hrs	Client Info		1		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>90	27		
Metal levels are typical for a new component breaking in.	Chromium	ppm	ASTM D5185(m)	>20	<1		
	Nickel	ppm	ASTM D5185(m)		0		
	Titanium	ppm	ASTM D5185(m)	>2	0		
	Silver	ppm	ASTM D5185(m)	>2	0		
	Aluminum	ppm	ASTM D5185(m)	>20	2		
	Lead	ppm	ASTM D5185(m)	>40	0		
	Copper	ppm	ASTM D5185(m)	>330	2		
	Tin	ppm	ASTM D5185(m)	>15	0		
	Vanadium	ppm	ASTM D5185(m)		0		
CONTAMINATION	Silicon	nnm	ASTM D5185(m)	<b>&gt;</b> 25	2		
	Potassium	ppm	ASTM D5185(m)		<1		
There is no indication of any contamination in the oil.	Fuel	ррпп	WC Method		<1.0		
	Water		WC Method		NEG		
	Glycol		WC Method	70.2	NEG		
	Soot %	%	ASTM D7844*	>6	0.1		
	Nitration	Abs/cm	ASTM D7624*	>20	13.3		
	Sulfation	Abs/.1mm	ASTM D7415*	>30	25.0		
	Emulsified Water	scalar	Visual*	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		4		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)		36		
	Barium	ppm	ASTM D5185(m)		0		
	Molybdenum	ppm	ASTM D5185(m)		62		
	Manganese	ppm	ASTM D5185(m)		<1		
	Magnesium	ppm	ASTM D5185(m)		1085		
	Calcium	ppm	ASTM D5185(m)		881		
	Phosphorus	ppm	ASTM D5185(m)		935		
	Zinc	ppm	ASTM D5185(m)		1184		
	Sulfur	ppm	ASTM D5185(m)		2487		
	Oxidation	Abs/.1mm	ASTM D7414*		30.0		
	Visc @ 100°C	cSt	ASTM D7279(m)	14.5	14.4		





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: CU0022798 Lab Number : 02634476 Unique Number : 5775629 Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received **Tested** 

Diagnosed

: 10 May 2024 : 10 May 2024

: 10 May 2024 - Kevin Marson

**CN RAIL** 76 INTERMODAL DR BRAMPTON, ON **CA L6T 5B3** Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T:

F: