**WEAR** CONTAMINATION **FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

Machine Id

OE525
Component
Diesel Engine

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		GFL0118561		
	Sample Date		Client Info		09 May 2024		
	Machine Age	hrs	Client Info		2894		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
VEAR	Iron	ppm	ASTM D5185(m)	>90	2		
VEAIL	Chromium	ppm	ASTM D5185(m)		- <1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185(m)		0		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)		0		
	Aluminum	ppm	ASTM D5185(m)		<1		
	Lead	ppm	ASTM D5185(m)		0		
	Copper	ppm	ASTM D5185(m)		<1		
	Tin	ppm	ASTM D5185(m)	>15	0		
	Vanadium	ppm	ASTM D5185(m)		0		
	White Metal	scalar	Visual*	NONE	NONE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>25	4		
751TTAIIIITATTI ST	Potassium	ppm	ASTM D5185(m)		0		
There is no indication of any contamination in the oil.	Fuel	ppiii	WC Method		<1.0		
	Water		WC Method		NEG		
	Glycol		WC Method		NEG		
	Soot %	%	ASTM D7844*	>6	0		
	Nitration	Abs/cm	ASTM D7624*	>20	4.5		
	Sulfation	Abs/.1mm	ASTM D7415*	>30	17.5		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	NONE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>0.2	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185(m)		1		
	Boron	ppm	ASTM D5185(m)	1	14		
The condition of the oil is acceptable for the time in service.	Barium	ppm	ASTM D5185(m)		0		
	Molybdenum	ppm	ASTM D5185(m)		57		
	Manganese	ppm	ASTM D5185(m)		0		
	Magnesium	ppm	ASTM D5185(m)		924		
	Calcium	ppm	ASTM D5185(m)	2942	1036		
	Phosphorus	ppm	ASTM D5185(m)		950		
	Zinc	ppm	ASTM D5185(m)		1108		
	Sulfur	ppm	ASTM D5185(m)		2528		
	Oxidation	Abs/.1mm	ASTM D7414*		13.1		
	Visc @ 100°C	cSt	ASTM D7279(m)	11 4	11.3		





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number : 02639582 Unique Number : 5788744

Received : GFL0118561 **Tested** 

: 04 Jun 2024 Diagnosed Test Package : MOB 1 (Additional Tests: Visual)

: 05 Jun 2024

: 05 Jun 2024 - Wes Davis

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 310 - Winnipeg #360 - 555 Hervo Street, Winnipeg, MB CA R3T 3L6 Contact: Joshua Lourenco jlourenco@gflenv.com T: (204)987-9600

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.