

**WEAR** CONTAMINATION **FLUID CONDITION** 


**NORMAL NORMAL NORMAL** 



## **IRON SHORING** 100-017

**Left Swing Drive** 

PETRO CANADA TRAXON 75W	/90 SYNTH	ETIC	( GAL	)			
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		LH0289422	LH0234717	
	Sample Date		Client Info		12 Jun 2024	16 Jul 2022	
	Machine Age	hrs	Client Info		4035	2025	
	Oil Age	hrs	Client Info		0	0	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		Changed	Changed	
	Filter Changed		Client Info		N/A	N/A	
	Sample Status				NORMAL	NORMAL	
WEAR	Iron	ppm	ASTM D5185(m)	>400	31	18	
All component wear rates are normal.	Chromium	ppm	ASTM D5185(m)	>10	0	0	
	Nickel	ppm	ASTM D5185(m)	>10	0	0	
	Titanium	ppm	ASTM D5185(m)		0	0	
	Silver	ppm	ASTM D5185(m)		0	0	
	Aluminum	ppm	ASTM D5185(m)	>25	0	0	
	Lead	ppm	ASTM D5185(m)	>50	0	<1	
	Copper	ppm	ASTM D5185(m)	>200	38	25	
	Tin	ppm	ASTM D5185(m)	>10	<1	<1	
	Vanadium	ppm	ASTM D5185(m)		0	0	
	White Metal	scalar	Visual*	NONE	LIGHT	NONE	
	Yellow Metal	scalar	Visual*	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>50	0	<1	
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	<1	<1	
	Water		WC Method	>0.2	NEG	NEG	
	Silt	scalar	Visual*	NONE	NONE	NONE	
	Debris	scalar	Visual*	NONE	NONE	NONE	
	Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	
	Appearance	scalar	Visual*	NORML	NORML	NORML	
	Odor	scalar	Visual*	NORML	NORML	NORML	
	Emulsified Water	scalar	Visual*	>0.2	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		<1	<1	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)	328	300	313	
The condition of the of is acceptable for the time in service.	Barium	ppm	ASTM D5185(m)	1	0	0	
	Molybdenum	ppm	ASTM D5185(m)		0	<1	
	Manganese	ppm	ASTM D5185(m)		<1	<1	
	Magnesium	ppm	ASTM D5185(m)	1	2	2	
	Calcium	ppm	ASTM D5185(m)	7	16	8	
	Phosphorus	ppm	ASTM D5185(m)	1145	1200	1222	
	Zinc	ppm	ASTM D5185(m)	3	12	9	
	Sulfur	ppm	ASTM D5185(m)	17909	20362	21676	
	Visc @ 40°C	cSt	ASTM D7279(m)	99.6	102	104	





CALA ISO 17025:2017 Accredited Laboratory

Laboratory

Sample No. Lab Number : 02642050

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 RONI/IRON SHORE EXCAVATING LTD. : LH0289422 Unique Number : 5799589 Test Package : MOB 1

Received **Tested** Diagnosed

: 14 Jun 2024 : 14 Jun 2024

: 14 Jun 2024 - Wes Davis

100 MACINTOSH BLVD VAUGHAN, ON CA L4K 4P3 Contact: Nathan Fernandes

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

nfernandes@roni.ca T: F: